#653404

¼ corner south ¼ 34 Salem 106-15E
north ¼ 3 Rock Dell 105-15E

No records.
6-7-1932 J Kerr B 8 P 14. L 34 Pete Lee.

found corner fence post in place which on finding rotted B T stumps pronel corner post as true corner location. Brass mark 2630.5

① 5" br oak N 74° E 201 lks. 132.66 orig govt tree.
5 br oak S 17° E 86 lks. 56.76

Orig above J Kerr. same ①
② S 17 E. 247 lks. 163.02.

10-21-75 Set C.I.M over ½" x 18" rod M&L. Corner falls under N-S fence

R.P.'s: Spike and CSD E side 6" Cedar NNE 86.4

Spike and CSD NW side blazed 12" Elm NE 40.42

Spike and CSD N side blazed 10" Elm E 24.68

Spike and CSD SW side blazed 6" Elm SE 38.84

Set by John Ball 10-1853

40.00 Set post for quarter section Corner

Dug trench per instructions

Burr Oak 5 N 74° E 201 links

Burr Oak 5 S 17° E 86 links