7-27-76 Set pipe in stake hole Found
3-23-77 Set CTA

#653406 LC

¼ Corner 33-34 Salem. 106-15.

No records

6-7-1932 J Kerr B8 P14 L34 Pete Lee.
run line betw 33-34 from north 5260'
no desc of point set if any.
- meas east to center 34 (on road) no desc, common land on north & south side. 2635.57 indicating corner of some sort, assumed or found.
- 5/16 north set iron M&L 1315.0
also iron in center NW ¼ 34. 1319 east above 5/16.

Dec. 1972 Co. Surv. - Set RR. Spike M+L. (also fd 1" iron - 6.7 So. & 0.4 E
RP's - W&I - on N. side AP #7409 - NoW. - 46.88
40 in 40" pine (3rd Pine from North) NE - 60.37

Set by Michael Karrick 6-1854

40.00 Set quarter section post in mound with trench pits and chared stake and Osage Orange seeds NE & SW.

~~R.P.'s No Shaft (3 corr)~~
~~Nail in PP #7409 N 80 51.95~~
~~Spike in pine (3rd pine from it) NE 60.95~~

7-27-76 Dug with backhoe  centered on M&L. Found 10"x10" black mark in clay with wood stake (wood piece) extending well down into clay. Drove 1½" x 3' pipe in stake hole. Corner 1.6 W and 2.0 N of M&L. Dug out 1" shaft found 6.7 S. and .43 E of M&L in 1972. Found shaft had been set over nothing. Did not set CIM Since road to be graded

R.P.'s: Spike and CSD in 15" Oak NSW 80.40
CSD in power pole NW 44.45
Spike and CSD in 15" Pine SE 49.09 (1987)
Spike in pine NE 60.30 60.31 (1987)

¼ Corner 33-34 Salem 106 15 (2)

#653406

3-23-77 Set a C.I.M over the pipe set in 1976

R.P.'s CSD in power pole NW ~~44.26~~ 43.92 (1987)

Spike and CSD in 15" Oak WSW 80.~~41~~ 39

9-24-87 C.I.M. Was leaning badly reset and took new ties as shown in pencil as 1987 ties

9