#653504

1/4 Corner South 1/4 35 Salem 106-15
North 1/4 2 Rock Dell 105-15

Set by John Ball 10-1853
40.00 Set post and drove charred stake for quarter Sec. Cor. Built mound & dug trench per instructions
Planted SE Osage Orange, N.E. Appleseed.

7-3-1980 (1980 Remon. BK) S 1/4 Cor 35 : Dug from a point 6' North of the t.n. (set on North edge of road) North 6', West 5', and East 9'. digging on North shoulder of road and in ditch. dug 2' deep on N. side of hole and 4' deep on South side. Fill to clay all over. Found

1' diameter black mark extending 1' into clay appx 1.0 West and 11.55 North of traverse nail
Found nothing further. digging to clear M & L.
9-5 & 8-1980 Dug from 3' North of the traverse nail to 16½' South of the traverse nail - clear across top of road by 4½' deep to clay. Found nothing
9-9-1980 Set a ½" rod on the corner in line with the fence North. Corner came 5' North of the center of the E-W road and 33' South of the North road fence and hinge the E-W fence at the 1/16 North midway to the calc E-W ¼ line Sec 35 and hinge the ~~fence~~ fence West at the 1/16 South @ prorated Bowl measure to the calc E-W ¼ line Sec. 2
Corner 60' East of bridge to be replaced
RP: Spike & CSD West side 27" Burr Oak NNW 88.20
CSD in South side pp # 44278 WSW 105.93

mark { T.N. S 11.55 W
PK in Fence post N 31.2 E