10-26-70 set 1/2" x 3' rod by line & meas from NE 34 over 1/16 stake & stone found double distance 1318.37.

6-30-72 set C/M over 1/2" rod. ①

1/4 Corner 34-35 Salem 106-15 2

T. Hunter Field Bk 14 p. 29 = fd stake in Center of Road as 1/4 post.

3-20-1889 Thos Fraser S 34 for H Y Scott unrecorded survey in small field book marked XXX #653506 found stake as 1/4 corner. 8 2/3 lks (5.72') east of direct line between 1/16 stake north of 1/4 corner and section corner S 34-35 Salem a "stone."

No meas of any kind on this line.

6-1932 J Kerr B 8 P 14 S 34 (NW 1/4)

Meas from NE 34 south to fence running east 2637.5 to determine mean N-S meas on 1/16 line of NW 1/4 34.

10-26-70 Co surv dug with tractor for 1/16 corner found limestone with large stake on S side - accepted stake as corner

over.

set 1" X 3'± galv pipe as corner. -
Meas North to section corner 1318.37
RP 1/16 mrkd on S side top tele box post
- Center 20" pine leaning SEly
- Center 18" pine
- SW Cor House
- eye ball from ℄ road; S side house
- very near center road. , 4' North fence running west.

| | |
|---|---|
| NE | 36.85 |
| ESE | 53.7 |
| SE | 69.5 |
| SE | 155.85 |
| S | 57.2 |

set Nail on orig random meas at 2636.15 near ℄ road
line over 1/16 stone Came 6.83 east
10-26-70 dug from 2'E of ℄ east over 5' found where extensive search had been made for corner very near entire area. ℄ stake in place was likely destroyed, dug 5' deep very wet, heavy rain during operation, read meas
see card #2

#653506 (2)

Card # 2 1/4 34-35 Salem 106-15

set 1/2" x 3' rod .59 S or 2636.74 and on proj line:
- after finding S 34-35 decided to place 26-27-34-35 east .6' as stone was leaning, this made stone set as 1/4 27-34 true N & L set 2640.55 now 2639.7 N & L.

final RPs: to 1/4 34-35 Salem

- .3' on N end field culv. 4' SW E 17.11
- " " S " " " SE 32.4
- small tard nail in small knot on E side PP #7479 up 2' E SW 98.93
- 7' west to ℄ road, 2' east to east edge road

10-28-70 moved NE corner Sec 34 .6 east.

NE Cor 34, 1/16 stone S and 1/4 34-35 as set on line

OVER

corner rod as placed lies 10.02' east of direct line between section corners.

- Xbs 5.72 meas N T Frazer that orig stake found lay east of direct line between S 34-35 and 1/16 stake north of 1/4 34-35 now is 6.68 which proves corners now in place very close.

- Meas north 1318.37 N & L
- Meas south 1326.28 to 1/16 fence line running east then to stone 1323.68 to C/M set in place of stone

2649.96

6-30-72. found rod. - set C/M by RPS to Culvert. placed 1/2" x 2' rod below C/M

set by Michael Karrick 6-1854
40.00 Set quarter section post
White Oak 12 N 47 W 5.00
Black Oak 12 N 43 E 3.08

1/4 CORNER 34-35 SALEM 106-15 (3)

1/14/92 VINCE FANGMAN TOOK R'PS #653506

TOP RIVET ON E END 15" CMP SE 49.01
(CMP RUNNING E-W ACROSS TWP Rd)

PUNCHED HOLE ON N END 18" CMP UNDER
FIELD DRIVE ENE 19.84

PK. IN SAME PLACE AS CONCRETE NAIL IN
SMALL KNOT IN P.P. # 7979 SW 98.93