1 6/9/92 SET 1" SQ PIPE/CAP IN DRILL HOLE, PACKED ROCKS AROUND PIPE (#1)

#701905 Winona County

section corner east 24-25 Quincy 107-11

5 parties re SW23

"a" 10-1896 W Fraser P595 no 541 & 23-4-5-6 found pile of stones seeming to indicate corner. all 4 BT in place checked very close to this location (a little north) took only BT trees as course seemed to vary.

Drilled hole in rock & placed sheet tin over hole. then placed red cedar stake over tin & piled mound around it.

Orig B trees - B oak N 73° W 55 lks - B oak N 42° E 50 lks

B oak S 60° W 37 lks - B oak S 67° E 100 lks

took new B trees.

16½ 39 1/4° 25.9

3" B oak S 84½° E 25 lks - 4" B oak S 39½ E 32 lks 07 27

-16 west 1" set stone 3 X 12 X 24 N 89° 45' E (1316.86 "to stone set B.
-16 south 3" set stake N 0° L 19.88. 1312.08.

to corner H" a corner post in mound.

Section corner in rough country W side river 30' N +

Gov'T Notes: 1853

N. 80.00 chains — Set Post for Corner

B.T.'s	Burr Oak	No Size Given	W 73° W	55 links
	Burr Oak		S 60° W	37 "
	Burr Oak		N 42° E	50 "
	Burr Oak		S 67° E	100 "

#701905 (#2)

Section corner E-st 24-25 corner 10T-11 West 19-30 Winona Co.

6/9/92 Cleaned up area 6-12' E of fence ext. which would Match Line & Dist from west. Used Dip Needle and found "∩" shaped Iron Removed & dipped again Fd 10" diameter Tin plate over dr.ll hole 2" deep in Bedrock as W Fraser described in his notes This area falls away to East on side hill So that Cedar Stake and Mound would be gone The Tin and Bedrock are 1' deep the corner falls under downed fence running Eastedly

Set 16" long 1" Sq Pipe with flange drive into Dr.ll hole By WC Fraser We packed Rock around the pipe to hold Position

The corner falls ± 8' E of N-S Fe

Spike and C S D in 4" Ash S 30° W 11.13 Ft

Spike and C S D in 12" Burr oak 45cm ∠s C P N 70° W 8.21 Ft

Ch scribed hole in top large stone N 20° W 13.52 Ft