X 10-9-74 ~~Set~~ Set a C.I.M. over a 5/8" x 30" rod and hub found. (1)

section corner, Township corner SE cor 36 107-11
NE cor 1 106-11
#703105

7-1890 Thos Fraser P444 no 429 1/2 Rod Co Line C Carter and others.

engraved stone placed by Hunter.

10-1896 Wm Fraser P595 no 541 Secs 23-24 25-26 Chenery 107-11.

found engraved corner by Hunter.
— 19.93 1/2 north to east sec. cor 25-36.

info. from Co. H.D. - Cert. of Loc. Book

Co H Dept. 10-62 - found engraved stone 2' deep, shattering placed stake on north side.
RP3 - pipe on fence line S. 33.7 - Disc Fpost S.W. 46.0.

1941 Co HD B125 PK found boulder & stake
Iron pipe L 33.7 - Sp FP SN 46.0
Rice Top FP N 68.05 - Hub NN 100.0

Mens mest to assumed corner 5265.2.

Sta 395+41.6

1970 Co surv stopped at corner. found very old disc in top of fence post N 68.05 lower than road.
- South side of road cut considerable. iron pipe mentioned gone in cut

---

Gov't notes: 1853
N. 80.00 chains - Set Post Corner, mack mound with Trench & Pits and deposited Rock 18x11x7 & Hawthorn Seeds.

#2

Twp Corner S.E. 36 107-11 Quincy
N.E. 1 106-11 Dover

703105

10-9-74

Dug with the tractor but found nothing as the area had been cut to subsoil. Accepted the location of the 2x2 hub we found as the cor. Location. We meas N. and it falls within W. Fraser's shortage (4.8' short in mile)

Drove a 5/8" x 30" rod with a C.I.M. over it. Corner falls in line with the fences running N.-S. and in ℄ of C.R. #9.

References.

C.S. disc top center of a 4½" conc. filled steel pipe S. 33.0'

Punched cross -!- on the [illegible]
4" pipe used as corner post. N. 51.08'

9-15-77 Found CIM broken to pieces. Can reset over rod set deep or by using two traverse points to West. Set RR Spikes at traverse points (H-2 in & Fielddrive So and on N edge blacktop - See Drwg)

July, 1923 E.C. Burns Winona County Surveyor
fd. stake set 2" x 30" pipe with 2" pipe as witness 33' South

---

7-18-95 T@ REF PIPE CR9L
4RT TOP CENTER WHITE TOP SILO NORTH TO TWP COR
3° 34' 59.5"
TO SE 36 (TWP COR) VA 96° 43' 07" dv 05 SLOPE 72.025 HOR 71.53

"703105" E

7-15-98
TD-55-88 99
+85°

✓ NE Sec Cor 1 Dover Twp 106-11

SE Sec Cor 36 Quincy Twp 107-11

Drilled hole 0.2' North ℄ ~ CSAH 9 (cedar)

25' West ℄ Field Drive North

C.S.D. in Top Center Wood Cor. Post North 65.09'

C.S.D. in Wood Fence Post SW 102.77

2' West of Fence South

In line w/Fence North