X 6-20-77 Set C Tc/p² #710205 (1)

section corner 2-3-10-11 Quincy 10 7-11.
See field Book 9 p. 61-67 and 68-72 2 3 9 Parties See NE 2.
10 & 11-1900 H Fraser P692-8 No 615 S 10-11
as E P693 - found red cedar stake in center pile of rocks.
marked, BT gone. (8" elm new B.T.) S 62° W 7 links, 25 lks east road.
1/16 West. No 41 P698 drove red cedar stake M & L. 19.81 1/2 1307.8'
1/16 East. No 8 P697 drove stake M & L 19.90 1314.4
1/16 South No 42 P698. drove stake M & L 19.97. Came by fence corner.
1318'

8-1928 J Kerr B-1 Page 19-22 1928 book # 2.
found red cedar stake & B true left as is.
Meas south. 5270.84 very stiff going south.
did not check for iron (set 1900 ak 1/4 10-11) M & L (2636.0'
(Gold notes says set Boulder)
(OVER)

1933 Co HD B73 P73 found red cedar stake, just east of 15" basswood tree. Mr Holdridge says this is only original govt corner in this vicinity.
Meas south 5279.86 W. Fraser 5272.08 J Kerr 5270.84

GOV. NOTES -1853- Wm A. JONES
SET SECTION CORNER POST 80 CHS NORTH OF 10-11-14-15
10" BLK OAK. N 25 W 95 LKS 62.7'
8" ELM S 48 E 45 LKS 29.7
7" ELM S 55 W. 6 LKS 4
POST IN MOUND AND PILE OF ROCKS.

SUMMARY MEAS S. ~~GOVERNMENT~~ GOVERMENT 5280'
W. FRASER 5272.08
J. KERR 5270.84
CO. H. DEPT. 5279.86
CORNER SEEMS TO BE IN BOTTOM RAVINE NEAR OLD TRAIL OR ROAD
SHARP ~~SLOPES~~ SLOPES E AND W.

Section Corner 2-3-10-11 Quincy #710205 10 7-11 (2)

6-20-77 found cedar stake standing as recorded 4½' East of 18" Basswood. Stake 32" long mitt 12" above ground. Removed stake to office and drove CIC/p[c] in stake hole. Drove steel fence post 2' West. Corner on E bank of dry gully. Corner approx 290' N of gate across old road through gully.

RP Sp + CSD So side blazed 18" Basswood N 4.51

Sp + CSD in 3½" blazed Elm SW 40.42

Note: Govt Note of lines N-S-E-W seem to indicate this corner is E of Frasers corner and up on bluff (This also puts ¼ Cor 2-3 in river as per Govt notes