SECTION CORNER 4-5-8-9 QUINCY 107-11 10/30/90
SET CIC/PZ

GUV NOTES 1853 - WM A JONES

710405

SET SECTION CORNER POST 80 chs NORTH of 8-9-16-17
8" LINDEN TREE AS CORNER TREE ?
STREAM 50 LKS WIDE RUNNING EASTERLY - NORTH 1 ch, 66 0'
CORNER IN Bottom LANDS
Foot of bLUFF south 2 chs 132"
Top of bLUFF south 5 chs 330
STREAM EAST 5 LKS WIDE 8 1/2 chs 560
south Line Sec 4 A [redacted] RUN ON ONE
WEST LINE ~~SEC~~ SEC 4 south 1/2 ROUGH North 1/2 LEVEL

8/21/90 TRAVERSED AS FIELD SO TO PT # 601 CURVED PT
WHICH FALLS NE'LY 15' FROM S 1/4 STUMP WITH
WIRE IN IT THE STUMP IS ± 22' SOUTH OF WATERS
EDGE

9/4/90 REMAINS OF FALLEN 36" TREE IS 14' EAST AND 7' SOUTH OF TREE STUMP TRAV. PT. STUMP 27½' SO OF S. WATERS EDGE & ± 40' SO OF CENTER WATER RUNNING E W.

10/30/90 SET (1C)P² IN HOLE AT FALLEN TREE LOCATION BELIEVING THIS TO BE GOVT. CORNER LOCATION. GOVT CORNER WAS A LINDEN TREE (BASSWOOD) WHICH WE FD LYING ON THE GROUND. SET SIGN & POST 2' NORTH OF CORNER EDGE OF WATER NORTH 27½' CENTER OF E-W WALK PATH SOUTH 105