X Set CIM over L.S. found
Set Sept. , 1974

#710904 (1)

¼ corner 9 - 16 Quincy 10 7 - 11
NE¼ 19.

10 - 1893 H Fraser P 538 No 499 F Elmore, J Fender.
found iron stake, claimed in place many years
Mr. Smith anere to corners correct position. Used only
to set center - quote "it is just ½ mile south of center"

10 - 1900 H Fraser P 692-8 No 615 L 2-3 9 parties.
10-11 see NE 2
could not find corner mon. Mr Smith was called and couldn't
find it. Its correctness now doubted. Run line N & L 39.98½
which came 2 rods east and 1 rod south of estimated location
of iron. Mr Smith & others now not certain he had found
original stake at time he set the iron stake. (over)

planted stone and stake at least 1 foot deep as it would likely be plowed out otherwise set M&L.

1/16 east planted stone 19.99 1/4 (1319.5 M & L. 18"x4"x4"

W Fraser Meas 2 line 2 9 5278.0' Corner as "R" in survey
John. B-1 P 19-22 got 5284.8 bottom of page 695.
1928.

5279.09 RB.

GOV. NOTES - 1853 - Wm A. JONES

SET 1/4 SECTION CORNER POST M+L 40.02 2641.32
CORNER ORIGINALLY IN BLUFF AREA. VERY STEEP AREA ON
N-SIDE
DOME shaped ESTIMATE NEAR 160 ACRES. NNE SLOPE
Section 16 rough & FULL of RAVINES & gULLEYS + SLOPES
COMMON LAND South - FARM LINE boundary North
massive Road construction controls FATE OF CORNER

#710904 (E)

1/4 9,16 Quincy 107-11

9-1974 Dug in pasture, fd W.F stone 18" deep
1/4 on the N.E side of the hillside south of
C.R. #2 set cim flush with surface

7/25/90 1/16 WEST OF 1/4 9,16 FD RR SPIKE SET
IN 1974 DOWN 2" IN BLACKTOP CR #10 IN
GOOD COND.