#710909

1

1/4 corner Center 9. Quincy 10 T- 11.
10-1893 Jr Fraser P538 no 499. S 9 Frank Amos
John Fender.
drove unmarked stake Midway on north-south 1/4 line as
west 1/4 corner gone. and parties involved did not wish to
spend the time to run west section line. Thus corner
could vary N-S if west 1/4 corner established later.
1/16 north drove stake M & L. 1976. (1304.2.
1/16 east drove stake M & L. 20.22 1/4 (1334.7.
10-1900 Jr Fraser E 1/4 & S 1/4 9 Changed corners above. no good.
See K P364.
See field BK 9 P. 65-79