X 9-13-1977 - Set CIM over 1/2" x 30" rod #1

#711006

1/4 corner 9-10 Dancy 10-11

10-1893 H Fraser P 538 No 499 Ld Frank Amos to John Fender.

found fence post hole where Peter Fender claims old corner once stood - placed stone in post hole and used same as corner (later proved wrong.

Corner No 1 (Found Fence Post Hole) 1.50 W.

1/16 - west set stake M & L 20.22 1/4 (13.34.7

1/16 north set stake M & L 19.82 1/2 (wrong) see below.

10&11-1900 H Fraser P692-8 No 615 L. 2-3-10-11 9 parties see NE 2.

See field BE 7 p. 68-77

Peter Fender changed his mind and other parties wanted corner claimed as lost so run corner in M & L. set stone 4 x 5 x 20. dug up old corner. Meas 39.84 S (2629.44 Corner K. P694

1/16 North - set stake. M & L 19.92. (1314.72) (over)

Drive stake marked 1/16 S.

1/16 east - set stone M & L 19.88 (1312.08) No47, P 698.
1933 Co H D B73 P73 found 4 x 4 x 18 limestone with red cedar stake on N side of stone
Meas N 2631.4 Meas S 2631.4. actual or mucculation of records 2629.44
8-1928 J Kerr Book - 1 (1928 Ty 2.) P 22.
notes that to check SE 9 - Quote "checked alignment from the corner on No. S. of Sec. 15 and found that it corresponded and the measurements OK. - Checked measurements N 1/2 mi. and then continued N. 1 mi. and found both corners and at proportionate distances." unquote no desc of either corner.
GOV. NOTES - 1853 - Wm A. JONES
SET 1/4 SECTION CORNER post M & L 39.96 1/2 2637.7
CORNER IN INTERS CROSS ROADS County Road #2 E-W.
twsp ROAD N-S
CORNER IN QUITE high FAIRLY LEVEL med contoured LAND.
← see 9-1974 Field notes in Quincy field book

#2

#71100

¼ Corner 9-10 Quincy 107-11

10-3-77 Set a CIM over a ½"x2' rod on the corner 1.84 W and 1.23 So of the triangular stone found in 1974. Corner found set M&L as per W.F. Set a stone approx 5"x5"x16" Found lying on ground (possibly Wilks) on N side of monument. Corner 12' N of E-W fence and 6' E of fence N

RP's CSD E side c.p. SW 13.34
CSD W side fence post SE 18.97