1

set ½"x15" rod in center of Appx. 8" sq hole into clay

Corner Calls in N-S Road 1974 #711009

¼ corner Center 10 Quincy 10 7-11.

9 parties

10 & 11 1900 W Fraser P692-8 No 615 S 2-3-10-11 on NE 2.

See field BK 9 - P68-79

No 39 P698 - set stone at true inters ¼ lines stone 1x10 x 20 & stake

1/16 west No 41 P698 - set stone M & L. 19.88. (1312.08.

1/16 east No 45 P698 - set temp stake M & L 19.89 1317.74

1/16 north No 40 P698 - drove red cedar stake M & L. 19.94 lines 1316.04 fence east

1/16 south No 38 P698 - set stone M & L. 19.94½. (1316.4.

1933 Co H D B 73 P 73 found 8 x 8 x 24 limestone with red cedar stake on N side.

Maple tree west 46.0 Maple tree N W 66.8

? Question This Corner (see size of stone) could be

9-6-1974 Co. Surv. - dug across entire Road with backhoe - did not find 8"x8"x24" L.S. & Stake found by Co. Hwy Dept in 1932. found Appx. 8" Sq. hole into Clay where stone possibly stood before road grading - Set ½"x15" rod in center of hole - 9-11-1974

Took R.P.'s - Center of 30" maple - N.W. - 67.8'
Co. Surv. Disc. in Sp #266 - West - 26.8'
Spk in Cor. fe post - E.S.E. - 15.0
Spk in gate post — S.W. — 36.12
Spk in 30" maple — N.W. - 46.56