4-5-73 relocated corner
6-27-79 set C.I.M. over bolt

#711705 (1)

section corner. 17-18-19-20 Quincy 107-11

11-1875 Hunter P287 no 283 & Hamilton S19.
found stone averaged by S H Hamilton as set by himself and surveyor. Redpath precisely where orig corner stood when mound & pits were plain
1/16 south set stake carefully N & L 19.97 1/2 1318.35 & Varrie

11-1892. Thos Fraser P500 no 477 S. 18 H Davidson, J Harvey
stone gone, dug rod square
Meas S 1/4 17 (a stone P459) west to S W 18 short 9 links.
Meas E 1/4 19 (a set corner P287) North to E 1/4 18 (P469) over 4 links
set stone at prop meas. -40.02 north -19.98 1/2 west. (over)

1/16 west set stone 4 x 8 x 14½ M & L. 19.98½.
1319.0

4-2-1973 road N & S to be graded by Forrest Tractor.
No fences east or west. common land east and west & N-S road
- started east from 1/4 18-19 corner post (could not find stone)
on 285' ⊙ scotch. - did not find to definitely identify the 1/16
stone recorded east (stone 4 x 8 x 14½ M & L 1319.0) set nail
in center N-S road on corrected offset.
R/R nail ① 29.95 NE to cone nail on NW side RR # 794
② 34.88 E to top point & angle corner post & base ✓

4-3-1973 dug with dozer with further research or measure.
hard frost down 2' about 2' or more depth of frozen ground.
found flat stone fragment Ref. ① 23.5 ② 28.5
found good flat stone [20"] ① 21.5 ② 22.1

See Card # 2.

Card #2 17-18-19-20 Quincy 10-7-11 #711705 (2)

4-5-73 Re-set 1/16 corner betw 1/4 18-19 corner post and original 17-18 19-20 by finding both iron bolts set by 2 hrs 4 Lasers 1892 N 18 E on N-S 1/16 line of SE 1/4 sec 18 Meas betw 2 bolts 1315.2 R 1321.0 See special card used this proportion to set SE 1/8 although it agreed back with 2 hrs 4 Lasers overall Meas. set Bridge bolt with ☐ head at corner 1/4 after grading

Meas mest to corner post corrected on 1/4 18-19 2631.4 } R 2638
" east to orig stone at 1/4 17-20 2625.76
" North to old post stub at 1/4 17-18 2637.93 } 2642 R.
" south to orig stone at 1/4 19-20 2631.04

RP's over.

RP's To bridge bolt set in new grade will fill over some.

22.81 N E ly To nail in pole (used to RP Stones & nails

476' N on projected section line to ½" rod N of road.
set 1969

Rod lies 8.68' S E ly from nail on log corner fence post

5.37 S ly from nail on S rod Pole now naked.

GOV NOTES 1853 Wm A JONES

SET SECTION CORNER POST 80 ch. NORTH OF 19 20 29 30

CORNER IN N-S TWSP ROAD

COMMON FARM LINES E-W both

ROAD is FARM LINE N-S

CORNER IN CENTER LEVEL LOW FLAT AREA STEEP E-S-W

6-27-1975 Harry S Johnson & Sons found bolt set 1973 graded out and lying filed in fill. Also power pole R.P. moved out. They reset the bolt 476.0 South of the reference iron (set 1973) and on line from the iron to V4 Cor 19-20. We checked the bolt location and found it correct. Set CIM over bolt. Comm 5' E & and 38½ N of center of field datum on East side of road RP CSD NW Side opp #794 NE 30.5 7