Sept 19, 1974 found Co. H.D. Rd over L.S.- set 3/4" rod on E. side of stone with 3/4"x15" riser. #911809
Top of Limestone was broken off but bottom full 3"x15"x15"±

X

1/4 corner Center 18 Quincy 107-11

11-1892 2hoo Fraser P500 No 477 L18 H Davidson J Harvey, Purvis

Planted stone at true intersections, 3x15x24.

1/16 north – set stone 3x15x16. M&L 19.77 1/2. (1305.2

1/16 east drove iron bolt M&L 20.01 1/2 1321.0

1/16 west - set stone 3x8x12 line and 19.95 3/4 chen 19.81 1/4.

1311.2 1307.62

P55

Co Hwy Dep B 146. found limestone set 3/4 risers

Disc Utl pole N.E 28.8. F post. S.E. 71.5

" P " W 26.5

" F post E 31.55

OVER.

1964 R.Ps. CHD

Lp D PP W. 36.92 - D Cor FP E 32.37

D FP NE 42.15

Meas rock 2614.55 to ¼ 7-18.

Note
Special Card to follow 1/4 18-19 Quincy 107-11.
4-2-73. ran and meas by hand from large corner post
corner set on east on 285' offset south noted pointed stone
at 1319.5' under E-W fence, set nail in center road
at 2622.46 Record 2638 11-1892 P500 Thos Frazer.
4-5-73. dug again at 1/16 found recorded stone 4x8x14½
lying at edge of field south of E-W fence washed out into field
I went north and found both iron bolts set on N-S 1/16 line
by Thos Frazer 11-1892 P500 recorded N & L 1321.0
found two irons 1318.2 apart or 2.8' short in 1/4 mile
- ran line carefully south projecting to 3/8" x 4' iron set
to replace stone 4x8x14½ washed out
over

North iron bolt. M&L betw ¼ 17-18 and center 18. set M&L 1892 P500 20 01½ 1321'

- iron with □ head up 3" just North ∠ Concrete base ∠ corner post (post completely rotted off.)

22.0 SE to 20 D nail on SW side 20" burr oak.

39.8 SW to 60 D nail on NW side 10" walnut.

---

- iron bolt with ○ head down 10" ↑ west ∠ woven wire fence 1318.2 south of above □ head bolt.

1.8' SE ly to steel post in fence 1st steel post S ∠ Plum log in fence row which is about 50' long and S edge log about 50' north ∠ corner.

- ⅜ x 4' iron dia ⅛ betw ¼ 18-19 and 17-18-19-20 set 1318.2 S above corner just north ∠ E-W fence 1315.85 E ∠ final Mdus E 1315.55 ¼ 18-19.