1. Oct 16. 1974 set a dimp tooth as cor 8' E. of C.R. #10

#712205 (1)

section corner 21-22-27-28 Quincy 107-11

4-1898 Wm Fraser P625 No 567 S27 C. Amos.

Corner gone, dug extensively, pioneer never saw or knew anything about corners. Tree rows planted east and west of corner area planted without any knowledge of their north-south location.

- set stone as corner on meas. below
- meas from 1/4 22-27 (stone set 4x6x16 in place of stake found) W. to 1/4 21-28 (stone found in center road) 7968½ (5259.2 set corner at 39.87 W 2631.42 - 39.81½ E 2627.79
- meas from 1/4 21-22 (stone found) South to S 33-34 (stake found and stone 4x7x27 set in its place) total 199.67½ 13,178.55 or 39.93½ (2635.71 per ½ mile

(over)

corner came 45 lks (29.7' north of row trees running east of south side road, 46 lks (30.36' south of row trees running east on North side road and 36 lks (23.76' west of tree row running south on east side road.

– Meas east from corner set 39.81½ (2627.8' west 39.87 (2631.4'
– " north & south 39.93½ (2635.71
– 16 south set stone ½ way between N W 27 and W¼ 27 meas or 19.96¾ (1317.85' not An N-S line only N-S meas. came on east side of road on line 3 pine trees running east.

BK 166 Pg 137

1945 Co H D (of 1917) Book 21 Page 28 Set 2 1 2 hub assumed.
Sp D PP SW 36.6 – Sp D PP SE 55.05 –
Steel corner post of fence NE 42.48

Oct 16 1914 C. S. [illegible]
Set ½" sq iron pin to mk. by [illegible] – Since 1945 [illegible]

K P.K.
[illegible] Bottle cap in [illegible] post
Bottle cap on P.K.

S W 63.34
S E 53.75
N E 72.05

SECTION CORNER 21-22-27-28 [redacted] QUINCY 107-11 (2)

71200

GOV NOTES 1853 WM A JONES

SET SECTION CORNER post 80 chs NORTH OF 21-28-33-34
CORNER IN ENTERS County Road #10 N-S
Twsp Road E-W

COMMON LANDS ON N & S sides CORNER
ELEV. 1132 CORNER IN high FAIRLY LEVEL AREA

Gov MEAS WEST 80.06 EAST 79.95