/ 7/13/92 County Surveyor's Set 4.5' Talspar Pipe/CIC #712404

1/4 corner 24-25 Quincy 107-11

10-1896 H Fraser P595 No 541 L23-4-5-6. 5 parties See Sir 23

B" corner lost, located 39.90 1/3 M & L - 2 mile line mens

set stake with 6X12X20 2633.73 as witness

1/16 east-1" set stone 3X12X24 -19.95 1/4 M & L 2616.86

1/16 west 2" drive stake 19.95 1/4 M & L 2616.86

GOUNOTES 1853 Wm ASHLEY JONES

SET 1/4 SECTION CORNER POST M & L 40 chs 2640'

CORNER HAS FARM LINES E-W-N COMMON S.

CORNER high ~~FAIRLY~~ FAIRLY LEVEL GENTLE SLOPE SOUTH, DOWN.

6/5/92 County Surveyor probed and fd stone, we dug and fd WF Stone 6X12X20, down 6", dug into clay, clay down 1 1/2 +

6/5/92 Cont.

Stone 2.4 south of existing corner post to fences N & W, Found Post Mark Just north of Stone Also 2½" Dark spot (Must have been Gopher hole) 2' North & 1' East of Stone, Found Nice 1½" SQ. Stake Mark on East Side of stone Down Into Clay 22", FD Post Mark 2' W & 1.0 south of Ex C.P. FD 3RD Post Mark 1½' W & ½' SO. of Ex C.P. Set ⅜" Rod at Surface.

7/13/92

Set 4½' Telspar Pipe/cic at location of Stake Fd 6/5/92 in place of ⅜" Rod Rp's 2.45' N₀ TO CSD in corner Post. Mon is 1.0' West of corner Post to Fences N & W.

1/16th East of 1/4 Cor 24-25 107-11 Quincy

Fd. Stone set by #9896 Top down 1' foot in old fence Row stone 3x12x24 it comes 1.8' North of present E-W Fence & 4' Easterly of C.P. To Fence E & W Set broken Iron pieces on E & West Side of stone below surface to help locate with Dip Needle