#712506

/

1/4 corner 25-26 Quincy 10 T - 11

10 - 1896 W Fraser P595 No 541. S23-4-5-6. 5 parties see SW23

Corner gone, found 2 B tree stumps. SW B tree blaze plain. "D"

NE B T. N57°E not N63°E set new stake from SW BT.

run N-S line, corner 10 links West of straight line and

11½ south of halfway making 39.95 North - 39.72 south.

south half of mile very rough land. Impassable for 26.67 26.52 actuality

---

- Orig B tree - 14" BO S50°W - 49 lks. 32.34 ✓

Govt notes Oct. 1853 15" BO N63°E 196 lks. 129.36 ✓

39.00 A STREAM 70 LKS WIDE COURSE NE & ASCENT BLUFF