8-23-77 CIM

#712704 (1)

1/4 corner 27 - 34 Quincy 107-11.

4-1898 Wm Fraser P625 No 569 d 27 C amac.

Coned not find any trace of corner.
used old fences and willow row running north and south from corner site. for setting center stake and survey north line section.

orig govt notes No 25 govt notes book. 107-11
80.06. set at 40.03. charcoal Trench & pits
no B trees

(OVER)

GOV NOTES - 1853 - Wm A. JONES
SET 1/4 SECT CORNER POST M+L 40.07 2642.0'
CORNER IN E-W TWSP ROAD
CORNER IS COMMON CORNER 4 FARMS.
CORNER IN high LEVEL LAND.

8-17-77 Dug from t.n. (set in ℄ + line of N-S fence) N 6', So. 5', W 5', E 5' by 5½' deep to clay. Found nothing.

8-23-77 Set a CIM over a ½" x 1' rod on the ¼ line from the N and in the ℄ of the E-W road. Corner .65 E + 1.5' N of the t.n.

RP. CSD N side pp SW 83.93
Punch hole top S. end 12" CMP in rd E SE 22.80
Punch hole top N. end 12" CMP in rd E NE 22.85
Corner in line with fence So end main line of the fence N and in 24' N of huge Elm on So side of rd.

1/4 CORNER 27-34 QUINCY 107-11 (2)

6-28-94 Co. SURV FOUND CIM WITH BROKEN TOP SECTION. WE DUG IT OUT AND USED THE + SECTION AS CORNER FOR MEASURING. #712704