8/23/77 SET CIM OVER PIPE #712705 #1

section corner 27-28-33-34 Quincy 107-11.
4-1898 H Fraser P625 no 569 L27 C Arnoe
set temp corner in center road for E-W and
on N-S mease porportion from ¼ 21-22 and S 33-34
199.67½ (13,178.55' or 2635.71 per ½ mile N & S.
- temp point 29 lks (19.14' south and 50 lks (33.0' east
& corner tree at SE corner church lot
- did not mease east & west so set no perm corner.
- this temp point used only to set N-S point for ¼ 27-28.
- ¼ 27-34 used fence & willow row south for line north

1913 Co HD B1 P57
16" cottonwood SE 61.3 Telgpole NE 35.5
mease north To E-W fence line 2647.0 R 2635.71

1945 Co H D. B 168 P 11 assumed corner set nut & nail

Sp. tree power pole NW 37.76.

" " " SE 51.76.

" tele " NE 34.91.

" R 5271.42

- meas south 5252.8

N frames. R P625

Sta 21-22-27-28 assumed 813 + 09 05

5289.3 5271.42

Sta 27-28-33-34 " 760 + 19 8

5252.3 5271.42

Sta S 33-34 " 707 + 67.5'

10541.6 10542.84

1921 Book # 36 C H D assumed Corner Measured

To 5258.0 south to stone Fd on township line

SECTION CORNER 27-28-33-34 QUINCY 107-11

#712705

GOV NOTES 1853 - wm A JONES

SET. 1/4 SECTION CORNER POST 80 CHS NORTH OF SOUTH 33-34

CORNER IN ENTERS CROSS ROADS
N-S COUNTY ROAD #10 E-W TWSP ROAD
CORNER IS COMMON CORNER OF 4 FARMS
ELEV 1124 IN high wide LEVEL FLAT PLATEAU
GOV. MEAS EAST 80.06 5283.96 WEST 80.02 5281.32

8-22-77 Dug down on E side of pipe. found area cut.
8-23-77 Drove pipe down and set CIM over. Corner in ℄ rds N-S-E-W
RPs CSD NW side telephone pole SW 62.01
OH CHD Disc in NE side pp NW ~~65.25~~ 63.18 (1988)
CSD SW side pp SE ~~65.06~~
TRAV PT MON 2" SQ PIPE/CAP 65.11 (1988)
SW 40 56'

Will Fraser corner here would be better
Further North. It has chosen point,
since as far as I know of the original
the corner [illegible] - 54' - has survived to the
present [illegible] of the [illegible]
[illegible] the old plat Book also shows
that the [illegible]
[illegible] yet no [illegible] was
[illegible] of no point [illegible]
could [illegible]
[illegible] the road
along the [illegible]
of Section 34

Section Corner 27-28-33-34 Quincy 107-11 #3
#712705

10-1976 Harry S Johnson and Son Co found 1¼" iron pipe down 4'. Accepted as corner for survey in the NW¼ Sec 34. Pipe in ℄ E-W road and ℄ N-S road

R.P.'s Spike E face power pole NW 62.70
Spike N face of telephone pole SW 61.73
Spike N face power pole SE 64.62

Measure S to 5/8" pipe set by Johnson 2619.80
W. th ⅜" ø pipe at 1172.60 S and then 551.39 ●

1917 C.H.D. Book #21 Page 38 Possible Corner

9/23/88 FD CIM IN GOOD CONDITION
CHECKED R P's