1 5-29-73 set CM. over stone found (1)
Cert 3-5-75 #713005

section corner west 30-31 Quincy 107-11
east 25-36 Viola 107-12.

10-1874 Hunter P262 no 261 S31 Peter Scherer etal.
found stake set by L D Hillman from stumps 2 B Trees
checked as closely as possible with same B Trees remain
set stone 5 x 8 x 11 in place of stake.
1/16 south set stone 3 x 5/13 x 24 20.02 1/2 N & L.
-1/16 east set stake for dist - 20.23 then 19.96 to N 1/4 cor
this distance short 8 links govt meas.

5-1887 Thos Fraser P431 no 418 S 30, H Kimber, F Walters, J Hirsch
J Tonford J & H. Pincock (INC)
found stone set by Hunter P262.
-1/16 east - set stone 5x5x18 line & prop dist - short 8 links - 20.23 - 19.96

6-1893 W M Fraser P 517 No 483 d 36 J Urban, Buck etal.
found section corner stone P 262.
-1/16 west - set stone 3 x 6 x 18 19.98 M & L
-1/16 center NE 1/4 36 set stone 4 x 5 x 30 at mtes lines.

5-29-73 found. orig recorded stone set 10-1874 by H.
set C/M. over stone found
Corner. 4.5' N of & road as traveled road.
2.0 W of fence N and S.
36.46 S. To rail in PP.
87.42 ENE. to rail in tele P.
Mean east to 1/16 found. 1335.58. R 1333.19 Hunter.
then 1317.62 E to 1/4 30-31 stone. R. 1317.36
See W 1/4 31 details of 1/16 stone and center N W 1/4 31.

#713005

SECTION CORNER W 30-31 Quincy 107-11 (2)
E 25-36 Viola 107-12

9/25/92 County Surveyor fd CIM down .2" in crushed rock rd., seems to be leaning north

10/28/92 County Surveyor dug out CIM fd stone below reset CIM over stone which moved top 0.2' South

RPS conc mkd in PP # 39421 South 36.45'
& E-W Twp rd South 4½'