#713009

1/4 corner center 30 Quincy 10 7-11

5-1887 Thos Fraser P431 No 418 S30 6 parties see SW 30.
set stone 4x8x24 at true intersection lines. 1315.05

1/16 north - set stone 3x12x18 - 19.92½ M & L. 1317.85
1336.24

1/16 west set stone 20.24½ then 19.96¾ to center.
(above meas from W¼ 30 east to center)

south - set stone 3x5x22 17.50 chs then 22.46⅔ to S¼ cor.
1155.0 1482.80

Co Hwy Dept 1943 B 146 P57
dug extensively found nothing. did not re locate corner.

stones found at 1/16 corners north & south

1/16 W OF CENTER 30 QUINCY

9/8/86 DUG SMALL HOLE (FROM A POINT 8½' S & 1½' W OF T.N. FOR 2½' S & 3' W.) TO CHECK CONDITIONS. AREA IN FILL OFF OF FIELD TO S. FD 2' OF FILL OVER 1' OF DIRT OVER CLAY. T.N. IS IN FENCE LINE WHICH APPEARS TO BOW N. ALONG WITH RD.

C/L between Center 30 and S 1/4 30.

T Fraser 5-1887 set stone 3x5x22.

17.5 chains south of center.

Co Hwy Dept 1943. B146 P57

Desc T.P., S.E. 28.7 Corrected 1943 orig 1941.

Sp fence Post SW 31.8

Sp " " NW 34.8 RPS to true corner not P.O.T. or P.O.T.

" " " N.E. 34.5

Note stone .95 east of direct line N-S 1/4 line

1943. 14821 R14828 from S 1/4 30

11565 R1155.0 to quite 30. computed

1/16 between Center 30 and N 1/4 30. B146 P57

5-1887 T Fraser set stone M&L.

3x12x18. 1946. 1314.2 M&L.

Co Hwy Dept 1943 found stone

Stone 1.0 east of direct fence

desc tele pole SE 23.0

desc fence post NW 47.7

desc poplar NE 45.6.

desc Cor F post SW 35.2

(over)

X 1/16th corner in section 30 found by Co Hwy Dept. (fallen south 30)

1/16 corner between N 1/4 30 and NW 30

5-1887 T Fraser set boulder 10 x 17 x 22

19.95 l west N 1/4

then 20.25 l to NW 30

Co Hwy Dep found boulder

dscc	tele pole	E	09.2
dscc	top fence P	S	47.8
dscc	poplar	W	27.4

90

713009"C 12-16-98 MW EA

1/16th west of Cen 30 107-11 Quincy dug 2½' x 2½' hole 2½' deep looking for T. Fraser stone much filtered in material with very little black dirt with mixed up Clay. Found nothing