1/4 Corner S. 1/4 Cor. Sec 34 Quincy 107-11
8-26-77 Set 3/4" x 20" N 1/4 cor Sec 3 Dovet 106-11
6-21-78 Set Cap bolt. #713404 (1)
Gov't notes: Sept 1853

Set Post for 1/4 Sec Cor & dug trench
one B.T. Bur Oak 10" N 53° E 184 links - 121.44'

7-7-1977 Dug with Backhoe from fence line north 14' feet west which covered M&L at 8' west of fence line north & 2' north & South of line - Faund nothing. road is right on the Clay.

8-22-77 Dug from fence E for 6' and 3' N & S found nothing.

8-26-77 Set a 3/4" x 20" bolt (with nut) at the corner on line and at prorated road survey measure. Corner 1/2' So & and 6' E of fence North.

R.P CSD in top of wood fence post SW 46.70

CSD in top of corner post NNW 35.09

CSD in pp # 991 WSW 188.50

6-21-78 C.H.D. dug out corner while patching road, then stuck rod back in. Set a C&M over a 3/4" x 20" rod from R.P.'s. Slight dip appears 2' East is probably the rod as put back by C.H.D - did not dig out since sounds deep.

1/4 CORNER	SOUTH	1/4	34	QUINCY	107-11 ②
	NORTH	1/4	3	DOVER	106-11 #713404

7-31-95 - FOUND CIM. SET 1" SN PIPE W/CAP 85' NORTH OF ℄ CR #9 2' EAST OF FENCE NORTH

T @ REF PIPE

3 RT TOP CENTER LARGE CUPULO NW OF COR TO S 1/4 34
212° 16' 54"

TO SOUTH 1/4 34
VA 89° 14' 35" du 05
SLOPE 84.98 HOR 84.97

Quincy Twp.

"713404" D 9-10-98

Placed Brass Plug at 1/4 Corner of South 34 Quincy and North 1/4 corner of 3 Dover.

"713404" E 7-15-98

N 1/4 Cor. 3 106-11 Quincy

SW4 Cor 34 107-11 Quincy

Drilled Hole 0.1' N. & crack x CSAH #9

6.5' East Fence North

C.S.D. in P.P. SW 139.40'

C.S.D. in P.P. SE 155.89'