1/4 Cor 33-34 5/19/89 SET 1" SQ PIPE/CAP #713406 107-11

Quincy

10-1976 Nave S Johnson and Co set 5/8" pipe on corner after finding three different nails in the same location but at different elevation (the deepest was 15" down) for Survey in the NW 1/4 34

Mean N to pipe at NW corner 34 2619.80

Corner 2' S of fence N and on line of fence E

RPs. Spike N face pp E 45.30

Spike W face PP SE 170.63

GOV NOTES - 1853 - Wm A JONES

SET 1/4 SECTION CORNER POST no L 40 chs 2640'

~~MADE~~ ~~mound pits~~

CORNER IN N-S COUNTY ROAD # 10

STA 27-28-33-34 760 + 19.8 PI 0°8'30" WEST.

STA L 33-34 707 + 67.5 PI 0°01' WEST

CO. MEAS 5252.3 RECORD 5271.42

FARM LINES E-W-N-S

8-23-77 Dug from pipe (removed) So. 1', N 7', and E 4' by 3' deep. Found nothing. Condition not bad — 4" black dirt beneath old road. Reset nail at surface.

5/19/89 SET 1" SQ PIPE/CAP # 15809 AT JOHNSON SURVEYING CO. LOCATION SHOT IN 1977 BY CO. SURV. THIS COR. LINES WITH MAIN FENCES E & W BUT IS 2.5' SO OF FENCE WEST; EAST AT ROAD; IS IN &
N-S CO. RD. #10 RP's
CSD IN PP NW 88.58
CSD IN C.P. WEST 61.20