1/4 Corner S. 1/4 Cor Sec 35 Quincy 107-11
N. 1/4 Cor Sec 2 Denver 10c-11
9/19/88 SET 1" SQ PIPE & CAP #713504 (1)

Gov't notes: Sept. 1853
Set Post for Q. Sec Cor
B.T.'s Bur. Oak 10" N 72°E 100 links
Bur. Oak 10" N 45°W 223 "

10-1902 W.C. Fraser Sec. 35 Carl Petzel
"F" - S¼ 35 - Could not find any corner so located small stake for use in this Survey 1/4 of distance from "G" (S.E. 35) West To a stone at the S.W. Corner Sec 34 and 2 rods North of line of cottonwood trees.
Meas E & W 39.89 ch = 2632.74
8-22-77 Dug on 1/4 line from N and in center of E-W road 2 3' N and 3' So of ℄. Dug 1½' deep. Found nothing.

2-88 Dig E½ E.T.V. to be midway between of 1977 nail location SW 34 and SE 35 as our N-S ¼ line = 15+36 (avg)

Also Hi [illegible]

9/13/88 DUG FROM 2' WEST OF N-S ¼ LINE OF SEC 35 TO 10' EAST OF ¼ LINE ½ FROM SOUTH EDGE OF PREVIOUS DIGGING SOUTH 2½'. ALSO UNDERMINED AT EAST AND OF OUR OLD DIGGING ON NORTH SIDE OF TODAYS DIG, FD POSSIBLE STAKE MARK ON WEST END OF OUR DIGGING NEAR ¼ LINE FROM NORTH, THE MARK IS 6.27' WEST & 3.57' SO OF TRAV NAIL SHOT AUG 1988

9/19/88 SET 1" SQ PIPE/CAP AT INTERSECTION OF N-S ¼ LINE OF SEC 35 & SECTION LINE FROM S.W. 35 TO S¼ 36 RP's C.H.D DISKIN P.P # 42928 S.S.E 33.41', PIPE IS ± 3' WEST OF MAIN FENCE LINE SO & S' WEST OF FENCE SOUTH @ ROAD & 1' NORTH OF E.C.R. # 9

1/4 CORNER SOUTH 1/4 35 QUINCY 107-11 (2)
NORTH 1/4 2 DOVER 106-11
#713504

7-31-95 - FOUND 1" SQ PIPE W/CAP, SET 1" SQ PIPE W/CAP 59' SOUTH OF 1/4 COR + 2½' EAST OF FENCE SOUTH.
T @ REF PIPE
4RT LIGHTNING ROD ON E END POLE SHED SW TO S 1/4 35
103° 17' 53.5"
TO S1/4 35 107-11 (1" SQ PIPE W/CAP)
VA 85° 06' 12" dv 03
SLOPE 59.39 HOR 59.17

"713504" D 7-15-96

✓ N. 1/4	Sec 2	10S-11	Dover	
S. 1/4	Sec. 35	10T-11	Quincy	
Set P.K.	Nail	0.1' South	℄ ^ CSAH #9 (crack)	
4' West	of Fence	South		
C.S.D. in	Top Center	Wood Cor Post	South	59.57'