~~6-11-74 set O.I.M. over 1/2" x 18" rod~~

#720104 (1)

1/4 corner 1-12 Viola 10T-12

over for record found-

No records known, except fact that many corners found known by older land owners which were set in some survey in Sec 1 Viola

8-16-72. land owner Mr Evans anera when he set massive corner post in concrete at his NW farm corner (an inland corner) he found over 3' deep a limestone rock crack, covered to that depth by soils from adjacent fields on slight slope. He reports setting corner post exactly on crack of stone. Did not dig yet visit area. can see from road.

6- 1902. Robt Fraser unrecorded survey found in old fieldbook No. 10 Page (42) as "F" Sec. HC Richardson at "F" corner found nothing drove stake and put stone in line and midway between E and L. 39.86. (2630.76 — 16N set stone and stake M&L Total 39.97½ (2638.35 to Center / a stone set inters ¼ lines

Gov't Notes W. Thomas A. Jones Oct. 1853

40.00 set temp. sec. post

79.99 Intersected - E. Boundary 6 lks W of corner

39.99½ set a sec. post at Acctg distance from with a Bur Oak 6" diameter N. 8° W. 50 lks. make a tree 4

~~79.99 to Sec. Corner~~

#720104 (2)

¼ Corner 1-12 Viola 107-12

10-29-81 ¼ Cor 1-12: Dug around 4" solid iron shaft c.p. Found shaft in concrete 3' diameter by 3½' deep. Impossible to look under. Dug East up to 5' on South side of the fence to cover line from the S¼ Cor 12 over the stone fd. at the Center 12 which came 3.55 East of the post but found nothing. Probed North well. Dug from fence South 2½'.

11-13-81 ¼ Cor 1-12, Viola: Accepted 4"+ solid iron shaft in concrete as the corner since there is no room to set monument of any kind and M&L comes just .05 South and .26 East of top center of post