1 8/12/91 Set 1" Sq Pipe Cap (1)

#720406

1/4 corner 4-5 Viola 107-12.

11-1891 T Fraser P465 no 447 S 5 L Slensberg

Corner gone in grading road previous year, Mr Dickerman owns willow rods north of road & fence south equal from orig corner. proved 4 rods set point midway for line W.

10-1894 Jr Fraser P553 no 510 S 4 E Dickerman.

corner non-existant as before set stone with slate by rods N & L. No mene. stone quoted in caption P465.

The caption of P465 says 40.11 1/2 west to center sec 5.

Gov't Notes over

11-13 1974 Dug with tractor & found nothing, ground was worn out

Gov't Notes W. A. Jones 1853

North Random 4/05

40.00 Set A temp. section post

South 24' E on true line between Sec 4/05

40.35 Set A section post in mound of Earth and Soil deposited Charcoal Made trench and pits planted Osage orange seals E+W of trench

8/12/91 County Surveyor Set 1" sq pipe cap at Gov't prorated position as also done by W. F. in 1894 when sub dividing section 4. this also matches points found & set in the interior of sec 4

1/4 CORNER 4-5 VIOLA 107-12 (2)
720406
8/12/91 Cont. Rp's
CSD in tele stub pole # 6000-16 SE 76.14
CSD in PP # 20753 NNE 46.72
℄ driveway south, east 32'
℄ C.R. # 24, south 3'