X 6-14-73 found Co drill steel ~~disturbed~~ Removed Rod replaced below row 24" galv culvert running diagonally under corner #720409 (1)
set 120 D as true corner from 2 stones south.

1/4 corner Center 4 Viola 107-12.

10-1894 H Fraser P 553 No 510 S4 E Dickerman.

set stone 4 x 10 x 24 at true inters lines

1/16 east set stone M & L.

1/16 west set stone M & L.

1/16 south set stone M & L

1/16 center of E 1/4 set stone inters lines.

1951 Co Hwy Dept.

found limestone set drill steel riser

over).

Disc	fence post	NE	47.41
"	Cor fence post	E	35.45

1930 Co H D B62. P12 found. Corner
Hub NE 52.3 — Hub SE 24.7
6-14-73 found drill steel and in checking below found 24" galv culvert running SE to NW almost directly under iron. Meas to corner from S - searched for 1/16. but 1/16 fence about 1321' S. then 1305 S to inters Crossroad soils at 1/16 show road down 30"+ but black soils below. dug 3' square and probed entire area. as no meas available seems 1/16 fence could be off some, enough to be out of area. must use cat and cover bigger area. something wrong somewhere.
N. Co. / N-1-5

Card # 2. Center 4 Viola 107-12. #720409 (2)
6-25-73. ran & meas elect- from 1/4 4-9 over 1/16 stone
North which came 1315.5 north where stone 3x6x20± found. 4' W of Center road. 5.5' N of. fence line running W.
RP 1/16 56.4 NE to Conc Nail NW side PP # 20776.
41.8 NW to Conc Nail SW side multiple line tel P.

back wiggled from Center 4 where point came 2.8' east of drill rod and nail set is .68' too far south to double 1315.5 meas - did not re the or reset true Cor.
- Cent line north found stone at N 1/4 4. at 2642.08 from nail or 2641.4 to true Center 4.

over.

7-5-73. removed Co HD drill rod and set 1x2x18 hub in its place driven flush.
- set 120 D on line set 6-25 doubling mean from 1/4 4-9 over 1/16. 1315.5 (no record) found meas N to CIM over stone at N 1/4 4. 2642.08 - center now .15' E of direct line as 24" Culvert runs SE to NW nearly under corner made no attempt to search for recorded 14x10x24 L stone.
32.95 E to old Co HD disc on S side corner post Co 35.45
44.92 NE to old Co HD disc on N side wood line post Co 47.71
32.6 E to conc. nail on S side power pole # 20 772
90.64 SW to orange cap on SE side tel pole.
109.63 NW to punched cross in □ lag bolt on E side terminal tel pole up 4'+.

1/4 CORNER CENTER 4 VIOLA 107-12 (3)

7/19/91 1/16th So. of Center 4 107-12, found Co. Serv.
1/2" iron set in 1973 at stone found
#720409
location RPS
℄ N-S twp rd west 6'
℄ drive way west north 8½'
1973 conc. nail in PP# 20776 NE 56.45

7/25/91 1/16th east of Center 4 107-12. dug for stone
Set by W. Fraser in 1894. Stone was gone but
found round shaped black mark running 4" into
clean clay 6" diam N-S & 7" diam E-W. Not big
enough or deep enough to be post hole, we think
the stone stood here. The stone mark is 0.6'
east & 0.4' north of the true nail. The mark lines
with fence west & south & is 1' NEly of new style C.P.