X Oct 25, 1974 fd stone (L.S. 2"x8" Top) 2½' deep in Road Inter.
Set CIM. over stone #720604 (1)

¼ corner. 6 - N Viola 109-12.

12-1873 Hunter P 236 No 238 S 5-6-7-8 S Holton.
found stake standing by fence corner set in
earlier survey from B trees.

- Meas east 40.00. } 2640.0'
- Meas West 37.85 } 2498.1
this line apparently near straight.

5-1886 Hunter P 407 No 396 S T A Heyn, T Bethke.
found hole where old corner stood in center road
in line of fence running north. set stone in place.
1/16 west set stone on line and 20.00 (1320.) chs west as requested
then 18.01 (1188.66' by owners in accordance with deed. over)

bearing 1/16 south S 25' E - bearing E-W sec line S 89°35 E
- 1/16 east set stone center road M & L. 19.98 1/2
bearing 1/16 above south - S 1/4° E - bearing E-W sec line S 89°40 E
indicating the north line of section 7 not quite straight

1930 Co HD B62 P6. found 4x6x18 limestone
6" below road surface.
RP NW iron pipe 46.65 - NE iron pipe 46.65
sta 106 + 45.3. center 7 80 + 12.3 2633.0
PI Δ 90° 23' Rt.

B279 P4 Co H D. 1963. Iro disc & corner only 60 D.
Meas west 2510.84. R 1873 (2498.16' R 1886 (2508.66'
Lp D tele pole S.W. 69.48 - Lp D PP SE 84.34
Lp D P P NE 66.24 R 1188.66 - 1886
Tops of fence in S 7. 1/16 west of 1/4 6-7. 1191. east of town line.

10-25-1974 Co Surv 1/4 Cor. 6-7 ② #7206O4

Dug with backhoe - found stone 2"x10"x15" in C.R.# 124. Stone was 2½' deep. Placed a large lag bolt on the N. side of the stone & set a C.I.M. over all. Corner falls 1' South of ℄ of C.R.# 124 & 2' west of ℄ of C.R.# 24 running South.

R.P.s

Center 18" Evergreen (3rd in row from South)	N.E.	85.45
C.H. Dept disc E. side tele pole	S.W.	67.23
Co. Surv. disc S.W. side tele pole	N.W.	71.36
C.H.D. disc N.E. side PP # 20106	S.E.	84.45
C.H.D. disc S.E. side PP # 20105	N.E.	68.44

Gov't Notes on reverse side

Gail Wells W. A. Jones 1853 1/4 cor 6-7
bar 8° E 7 E
40.00 set a temp see post
East on true line between sec 16 & 7
course N 89° 45' E
38.37 set a sec post Bur Oak 14 in N 51 E 124 lks
Bur Oak 7 in S 56 E 134 lks

7-30-96 Found CIM down 4" in Blacktop CR #24
in good condition.