X 11-13-73 set C/M. over 1"4x28" pipe and ore stone base. ①

¼ Corner 7-18 Viola 107-12.
#720704

6-1876 Hunter P298 No 293 S18 A Whitney D Howard.

corner gone, 8 trees gone, "root & branch", run line east 77.76 short 87 lks, set corner carefully 38.20 chns 39.56. 2521.2 2610.96
Bearing E & W N 89°37'W bearing south N 10°E

5-1886 Hunter P407 No 396 S.7 A Heyn, F Belka, etal
corner missing having been recently plowed set stone 2x10x20 on line and post prop. 38.20 west 39.56 east N 89¾ W
bearing of line north to stake set center 7. N ½° W.

5-1886 Hunter P408 No 397 S18 August Fratzke.
found & used stone set center road P407.
⅛ east set undecided corner. 19.78 M&L N 89¾ W Bearing S. N 10° W.
1305.48

11-1891 2hor Fraser P466 No 448 L18 L Hines.
found Hunters stone which had been reset after plowing
& out grading roads, reset as close as possible by road crew.
on running line found corner should be. 2' S and 1' west
left corner stone in place however.
-Mean east 39.51 1/2 26 p 7.99 by gent prop. (Hunter 39.56).
-1/16 west set stake on line and. 19.76 then 18.41 to cor.
total mile 77.68 1/2 (Hunter 77.76) 1304.16 1215.06
-1/16 south 19.95 2/3 M & L. a stake 1317.14 1211.6 1306.62
-1/16 center NW cor 18 set line E-W 1/16 prop dist 18.35 3/4 - 19.7 3/4.

1957 Co Hwy Dept limestone with 1" drill steel rises.
Disc - tel pole. SW 62.5 - Disc F post E 51.35 - Disc F Post W 48.18.

Card # 2. 1/4 7-18 Vola 10 7-12. #720704 (2)
found 3 county H. Dept RP discs but corner posts
were leaning and shifted and would not prone
drill rod claimed as corner was over stone.
11-13-73 dug with air hammer and shovels.
found drill rod down 16". continued digging and
found 3 wood hubs in various locations near rod.
found limestone about 3/4 of recorded 2x10x20 lying
flat with base of stone at its original place. placed
1 1/4 x 28" pipe over stone with C/M above flush with road
surface Meas S to center 2636.25 R 2634.28 T.F.
2610.96 H
Meas W. 2517.85 R 2521.2 Hunter F 2602.41 2607.99 F.
2519.22 T. Fraser.
Gov't Monuments over RPs.

RP CIM 1/4 7-18 Viola

62.62 SW to 16D thru bottle cap and Co H D disc on SE side tele P. up 5' level road top.

103.5 SSE to concrete nail west side PP # 20131.

Corner stone carne. 1.58 North .83 west of drill steel.

Corner lies 1.8' north of direct line.

Gov't Notes W. A. Jones 1853 7+18 East Random bar S 39° E

40.00 Set A temp see post

East on true line between Sec 7+18

38.63 Set A see post 40 Course N 89° 4X' E

Burr Oak 10 in N 66 W 17 Lks

Burr Oak 14 in S 70 W 275 Lks

Card #3 1/4 7-18 Viola 107-12 #720704 (3)

7-30-96 Fd CIM 4" deep in blacktop CR#124.
Set PK Nail @ surface at monument location.
Bottle cap in PP #20131. S.S.E. 103.49
The corner falls in ℄ of CR#24 ± 3' North of hard to see Sec line fences E & W.