X 11-14-73 set 3/4 x 15" pipe in center old post hole (1)

#726705

section corner west 7-18 Viola 107-12

east 12-13 Haverhill 107-13

6-18 76 Hunter P298 No 293 S18 A Whitney D Howard.

corner missing, all B trees gone but 1 stump, which proved correct testimony of Mr Leary that corner post in place had replaced orig stake in mound, left corner fence post as found.

- Meas east 38.20 to undescribed corner set on line and govt. prop. entire mile being 87 links short of record. 2521.2
- Meas south 40.00 to stone placed on govt stake site.

5-1886 Hunter P407 No 396 S 7 A Heyn, A Bettcha etal.

found corner post in place - left as is. P298

- Meas east 38.20 to stone 2x10x20 set this survey. 2521.2 N 89 3/4° W
- Meas north 39.91 to stake set M & L " " 2634.06 S 1/4° E

5-1886 Hunter P408 No 397 S 18 August Fratzke.
found corner post & O' Learys
- mean east 38.20 to stone N 89 3/4° W.
2521.2

11-1891 Thos Fraser P466 No 448 S 18 L Hines
found corner post P 298-407-408.
1/16 south set stake 20.00 1/16 = 1320.11 M & L for line east. ~~1320.66~~ = 1320.11
1/16 east set stake on line and post prop - 18.41 - then 19.76 -1214.06.
total mean for mile east 77.68 1/2 record 78.63 1304.16
making wlat half. 38.17 (2519.22 east. 39.51 1/2 (2607.99
(note N 1/4 18 change on 1/4 7-18 card) (reference below)

1957 Co Hwy Dept. limestone 1" drill rod riser. 1/4 7-18
Elec tele pole. SW 62.5
" fence post E 51.35
" " " W 48.18.

Card # 2 West 7-18 Viola East 12-13 Haverhill (2)
11-14-73 ran and meas line between 7 & 18 on 30' (S)
south
#720705
found 6" post hole abont 1' SEly of present corner post,
placed 3/4" x 15" pipe with elbow down in old post hole.
102.2 east to nail N side 18" oak. 2nd tree east.

Measurements S computed 2636.57 R. 2640.22.
E elec. 2517.85 R M 2521.2
TF 2519.22.
then to 7-8-17-18 2602.41. R M 2610.96
from 1/4 7-18 TF 2607.99.

Govt Meas. dens. 1853
Set Section corner post 80 chains North of
Bur Oak 10" S 85 W 115 lks W 15-19
Bur Oak 8" N 78 W 112 " "
Bur Oak 4" S 80 E 23 " "
Blk Oak 6" N 21 E 129 " "

11-29-86 Vince Fangman fd. 3/4" pipe 0.6' South and 0.3' West of Corner post to Fences west & North. Set Studded-T Post 0.5' N.W. of pipe.

R.P.S. 8d nail in Wood Post West 15.69'
8d nail in R.R. tie Post S.W. 18.43

There is a Corral Fence South and East of this Cor.

Notice 1973 corner SE'ly of C.P.

CARD #3 West 7-18 Viola East 12-13 Haverhill (3)
8-1-96 Fd pipe set by R.B. in 1973 & Fd & used
by V.F. in 1986 Set 4' long CIC/ρ^2 over pipe #720705
fd. The corner falls .6' so. & .3' west of C.P.
to Fences W & N V.F. Ties still there & good.
There is an E-W lane Fence 16' South of Corner
& a N-S Lane fence 21' East of Cor