#720706 (1)

/

1/4 corner west 1/4 7 Viola 107-12.

east 1/4 12 Haverhill 107-13.

5-1886 Hunter P407 No 396 ST A Heyn F Bethke.

Corner gone, no evidence by digging or there was no knowledge of where it originally stood.

set stake M & L. 39.91 Bearing N-S line S 1/4° E

2634.06. bearing E-W 1/4 line N 89°50' W

1/16 east set stake not marked at line and 18.10 1194.6

then 20.00 To center see T. 1320.

This done by order of owners as deed requested.

Bearing of 1/16 line north S 25' E

9-76 Dug 3'x3' at intersection of line from W 1/4 Cor 12 over Center 12 and line from NE 12 to SE 12. Found nothing. Come in deep fill in E-W fence line.

Good Notes down to 1853
Set 1/4 section post & mtd. No notes from set

Bur Oak 10" 5 30 E 20 lks
Bur Oak 12" N 35 E 25 lks

10-18-96 DUG FOR T. HUNTER STAKE SET M+L IN 1886 + ALSO COVERING 1/4 LINE FROM WEST WHICH COMES 2 1/2' SOUTH OF M+L POSITION. DUG FROM 7' EAST TO 11' EAST OF T.N. + FROM 1/2' SOUTH TO 4 1/2' NORTH OF T.N. CLEAN CLAY LINE ON NORTH

1/4 CORNER W 1/4 7 VIOLA 107-12 #720706 (2)
E 1/4 12 HAVERHILL 107-13

10-18-96 CONT: SIDE OF HOLE IS 4' DEEP. THE SOUTH SIDE IS 3' DEEP TO CLAY. THERE IS NO BLACK DIRT LINE. THIS IS A SEDIMENT AREA FROM NE WITH HILL ON NORTH SIDE. THERE WAS MUCH GOPHER DIGGING IN DEEP CLAY ALL OVER THE HOLE. THIS AREA HAS BEEN FILTERING IN FOR YEARS WITH FENCE LINES WEST + SOUTH STOPPING THE FLOW. FOUND NOTHING.

5-21-97 SET 4' CIC/P² @ M+L POSITION. SET SIGN + POST WSW 9½'. THE CORNER FALLS IN BEAN FIELD DOWN 1½'.

1' E OF FENCE LINE SOUTH (MAIN LINE)

2' N OF FENCE ROW WEST.