1 9-24-1979 Set CIC. #720804

1/4 corner 8- 17 Viola 10 7-12.
8-1900 R Fraser P688 no 611 d8 Iron Board.
found old stake about 2' west of corner part of fence.
but in line of fence north-south-east
drove new stake (no mark or bearing).

~~Govt Notes~~ 1853 East Random Line S 8°33'E
40.00 Set a temp sec. post
West on true line between sect. 8&17
bar S 8°9'E
40.06 Set a Sec post B. Oak 10 in N 55 W 52 lks
B. Oak 10 in S 60 E 180 lks

9-21-1979 Dug from the traverse nail set 1'ESE of the corner post to fences N-S-E, North 2½', South 2½', East 1' and West 4' by 2½' deep to clay. We found the stub of one old post 1.5 West of the t.n. and the stub of another 1½' West and 1½' South of the t.n. Found nothing else.

LRP { small nail in fence post E .9 }
{ spike in fence post S 5.87 }

9-24-1979 We projected the Northerly 500' of the fence South to the area of the corner and came 3' West of the t.n. We set a CIC on telepo in line with this fence South and West of the corner post. The fence East was too crooked to line up very accurately. The corner is .6 North and 3.15 West of the t.n. We put a survey marker sign on the corner post 2'ESE

RP: CSD on N. side of corner post E 2.23