X ~~A-13-73 set C/A over orig boulder.~~ (1)
11-1981 CIM destroyed. See C.S.
#721104

1/4 Corner 11-14 Viola 107-12
6-1893 W Fraser P518 No 484 & 11 & Purvis, & Richardson

Corner missing, no evidence or knowledge of corner, set boulder 8 x 12 x 16 with limestone on top 2 x 8 x 12.

M & L 39.94 2636.04 S 89° 40' E
1/16 east set boulder. 6 x 8 x 18 M & L 19.97 1318.02.
1/16 north set stone 2 x 6 x 20 M & L 19.89 1312.74. N 22' E
1/64 north (11) set stake M & L above 1/16. 9.94 1/2 656.37.
1/16 center & E 1/4 11 set boulder. 8 x 18 x 18 enters lines
1/64 south (12) of above 1/16 cor. set stone 2 x 8 x 22 M & L 9.94.
on 1/16 line 656.04.

over)

6-1893 W Fraser P519 No 585 & 14 R Palmer, F Frank
J Dubbs, R Richardson

found corner P 518

1/16 east P518 found boneder.

1/16 south set pile stones with 15" stone on top M & L 20.05

1933 Co Hwy Dept. B 73 P 71.
found 6 x 18 x 16 boneder. (lower one. P. 518.

18" pine tree NE 37.1
14" birch tree E 31.7.

Used fence post as Center 11 - set stake as 1/16 corner
M & L 13 18.45 for center county road no. 2.

Card #2 1/4 11-14. Viola 107-12. #721104 (2)

7-13-73. Ran elect line from. Center 14 as found badly tilted stone (7-16 moved center. .86 N - .30 W.) easily found 1/16 corner between Center 14 and 1/4 11-14. (see Center 14. for all 1/16 corners adjacent to Center 14.) - dug with tractor and found. 8 x 12 x 16 boulder. recorded limestone gone. - broke off part of C/M and placed over boulder, glass etc. with glass. Meas south to 1/16 stone found. 1322.0 R 1323.3
4 3.0 3. NW ly to conc nail in small knot NE side tie P. 85.4 ENE to natural crease in L side center 4 2 rd crotched pine in N row pines about 4 ch or 5 ch pine in Row.

Gov't Meters More RPs over.

35.0 N to eye line north row pines E.

24.0 4' N & due E to center single only birch.

---

7-1933 C.H.D. Book " 73 page 71 found stone at 1/4 Corner. assumed fence line at Center of sec 11 2636.9 North of stone fd. Set 1/16 Corner (a stake) m & L 1318.45

600 Links EAST Random 11 & 14 W. A Jones 1853
40.00 Set A temporary section post
West on true line between Sect 11 & 14
Bar 9° 06' E
35.00 A Stream 5 lks Wide course N
40.00 Set A sec. post Bur Oak 9 in N 18 W 112 lks
Bur Oak 8 in S 70 W 208 lks

#721104 (3)

1/4 Corner 11-14 Viola 107-12

10-30-1981 1/4 Cor. 11-14: Found 3/4" Taylor pipe at road surface which came 35' South of eyeline of north row of pines E and ≈ 85.4 WSW of natural crease in So. side pine as described in 1973 All other R.P.'s gone. Removed pipe and dipped for CIM but got nothing. Set pipe back. Should dig for stone

11-11-81 1/4 Cor 11-14: Removed pipe to dig down to stone to reset CIM at corner. Dug 3½' deep but were still in road fill so filled hole and reset pipe (Could dip nothing). Corner should be dug with backhoe and/or run in from So and

Center 14 Fd in 1973.

CIM apparently destroyed in road grading. See County Survey