X 5-28-1974 Set CIM ~~on~~ Kerr's Bolt ⅝ Part of L.S. (1)
Set ⅜" Pipe - 8" Long over Bolt with CIM above. #721606

¼ Corner 16-17 Viola 107-12.

7-1870 Perry P130 No 162 L 16-21 A Robinson
all B trees gone, found stone set by neighbor not claimed as correct, just close, having lost orig accurate stone by road crew. set stone 2 x 3½ x 20 with small stone on west side as witness M & L 39.76½
8" burr oak - N 29¾° E 115 lks blazed tree.
removed other stone found as corner

5-1933 J Kerr B 8 P 77.
set limestone 2" x 2½" x 14" packed in broken rock.
with ⅝" x 10" iron bolt below. lines E-W fence. over)

– Meas east line sec 17 5255.8 south to sec cor.

Perry 5249.0.

set stone M & L 2627.9

RPs lines fenced east & west.

Center cottonwood 36" NW 25.8

1974 RP's

Co. Surv. disc S. Side R.R. tie corner post W. 28.05

" " " E. side P.P.# 39253 S.W. 84.00'

Corner falls in line with E.-W. fence in the west wheel track of the N.-S. Road.

Viola 1/4 corner 16-17 #721606 (2)

Coat Notes on reverse side

Gov't Notes W. A. Jones 1853

1/4 corner 16+17

40.00 set a station post

Bur Oak 10 in N 78 W 152 lks

Bur Oak 8 in N 53 E 40 lks