X 6-3-1975 - fd old Stake or Post set ⅝" rod with CIM. over it.
#723006 (1)

1/4 corner west 1/4 30 Viola 107-12
east 1/4 25 Haverhill 107-13.

6-1873 Hunter P227 No 230 S30 E Derby, D Madden.
orig corner missing. Mr M Mark "avers positively" he helped set corner post (now standing) in spot in mound & puts where orig stake was pulled. this made the corner 2 rods ± too far north. As this was to his disadvantage accepted corner post as true corner. Meas - south 40.42. (2667.72
- meas north 39.53. (2609.0 - total mes 5276.72

5-1874 Hunter P242 No 243 S25 J. Lawler, M. McElligott found marked corner fence past P227. left as is.

(over)

- 1/16 west set stake M & L 19.89 S 89° 38' W for line south.
- 1/16 north set stake M & L 19.97 N 10' E

7-1874 Hunter P258 no 259 S 19-30 John Nevins used corner to set 1/16 east - center already established actual meas east 38.10 - record by computing mean of N & S section lines. 38.81 (north line equally short). 38.81 : 38.10 :: 20.00 : 19.63 leaving 18.47 as meas east to 1/16 corner. apparently a stake set for line north. to set
- 1/16 corner as center NW 1/4 30 by inters. lines.
- 1/16 north set corner M & L 19.76 N 10' W.

Gail Notes
[illegible]

#2

¼ Cor W ¼ 30 Viola 107-12 #7230006
E ¼ 25 Haverhill 107-13

6-3-75 Dug with backhoe and found cleaned stake 2' deep in clay (.5± N of plotted Hunter measure and 1' ± E of line between section corners)
Set C.I.M. over ¾" x 18" rod. Corner lies 5½' N of local fence east and in ℄ N-S road.

R.P.'s C.S.D S. side corner post ESE 29.53
C.S.D. N side gate post NW 32.96
C.S.D. S. side most southerly of pair of power poles in field NW 274.8