X 6-2-1970 set ½"x2' rod over 4' steel prop handle with pieces of orig stone on E-W sides
11-19-74 Accepted as P.I. ind as corner

¼ corner south ¼ 31 Viola 107-12 (1)
#723104
North ¼ 6 Eyota 106-12 2

5-1871 Hunter P184 No 195 L6 W & J. Elliott.
found stake in center road mound & pits still visible.
1/16 west 19.88 chen 17.91 to twp cor. govt prop S89°50W
1/16 south 20.03 chen 19.94 to center sec 6. N¾° W
1/16 east 20.00 M & L.

5-1872 Hunter P206 No 214 L31 P & E. Daley.
found stake in center road. P 184 - set stone 4x8x16.
- meas east 40.00 to stake found.
- 1/16 west set stone 3x8x15 M & L. 18.89 according to (orig)
R 2493.5 total deed.

Co Hwy Dept 1937 B 88. P12 & P76. R 2493.5
found limestone measured to hwy cor 2504.6
FP-NW 54.0 — FP NE 49.5 — FP SE 33.6.

1966 J Kerr these ties all gone - black top
no riser - didn't dig for corner.

---

add Ties - Lpm FP south 67.3 - Hub L.W. 100'
Lpm FP N 54.1 - Lpm FP NE 49.3.
these ties could be P.I. RPs which may be corner or not.
Sta PI 316+76.8 - P.O.T east 330+00
1323.2 RP to P.O.T Lpm pine N 67.85
Lpm maple NW 88.1 - Lpm pine NW 62.1
Lpm pine SW 43.25 -
Sta Twp cor 291+72.2 - S¼ cor 316+76.8 SE cor 343+21.7.
total mile 5149.5 west 2504.6 east 2644.9
R 5133.5 R 2493.5 R. 2640

#722104 107-12 (2)

Card # 2 S¼ 31 Viola
N¼ 6 Eyota 22" 106-12

1937 CoHD B88P76 found L stone 2' below surface.
F.P. NE 49.5 - F.P. NW 54.0
F P SE 33.6 - Sp F.P. S. 67.0
Hub SW 100.0
These RPs coned to PI spike which is on east side of corner stone. Meas E 2644.9 W. 2504.6

Sta by CoHD Inspector. 291+72.2 - 2504.6 about 3' fill found correct.
Sta " S¼ 31 316+76.8 - 2645.4 1' fill
Sta " " S 31-32 343+21.7

6-2-1970 Co surv. dug thru black top & set base found stone, a limestone somewhat thicker than record maybe an inch. stone was not deep and tilted slightly toward the east below old road bed. placed a steel mag handle 1"x 4' where center

A stone base where a hole some 6" deep below stone indicated a wood stake, set orig stone pieces on E + W sides Much glass etc. set ½" x 2' rod near road surface. Corner lines fence north exactly and very near center road. No possible references available so placed ⅜" bolt with nut and 4½" long under fence north (up 2") on transit line with base of large black oak corner post of north cattle yard fence west some 4 to 5 hundred feet north. set rod at exactly 100.0'
Meas west 2502.2 - east to S¼ 32 found. 5284.0
Meas bkup on to Co nail 5144.55 corner found .65 east of nail.
5145.1 - 2502.2 or 2642.9 or close to 2643.0 from S¼ 31 to stake found at S 31-32. which fell 3.14' W of direct line from Twp corner mer. S¼ 31. making S¼ 1.57' N of direct line

11-19-1970 recovered C.H.D. PI rod. 4" corner
L.P.'s corner falls 0.13' North of Conc. center line
punch hole top lug clamp E end 18" C.M.P. S.E. 45.55
" " " " W end 18" C.M.P. S.W. 48.12

1/4 Corner South 1/4 31 Viola 107-12 (#723104) (3)
North 1/4 6 Eyota 106-12

sept., 1863 P.C. Compton Pg. 77 No. 114 shows 1/4 Cor. used to set Center Sec. 31 at intersecting lines.

Gore Notes

40.00 Set post & stone witness posts for quarter section corner 15 lks marked with cross. Planted S.E. Ditch 0.5 lks. N.E. Mark cross.