#723206

1

1/4 corner 31-32 Viola 107-12 (1)

5-1872 Hunter P206 no 214 S31 P&E Daley.

Corner gone, no evidence or knowledge,
set temp point M & L. 39.84 1/2 for line west.

6-1873 Hunter P226 no 229 S32 J Madden, C Shellman.

Corner gone, renewed search for corner or knowledge of it.
set stake M & L. 39.84 1/2 for line east. S 10' E.
1/16 north set stake M & L. 19.92 1/4 for line east S 10' E.
line east due east & west. Can't w. (over)

11-1968 J Kerr BK 98 P. 37

Meas N-S line . 5263.5 A 5258.8 R.

Set ½" steel Rod 2631.75?

1/16 fence east north to section stone & C/M 1314.2A 1314.7R

no fence east and fence west on common land about

2646.2 from south. instead of 2631.75

– set temp point 14.45 south & run aerial over angle

iron corner post as center 32. line came about 4 feet

north of midway on east line 32 indicating either center

of W¼ needs adjusting – meas east line twice.

Govt Notes 1853 W. A. Jones

40.00 Set A section post in mound of earth

+ soil deposited charcoal post in mound of earth

and pits planted Osage Orange set

E+W of trench

1/4 Corner 31-32 Viola 107-12 #723206 (2)
Sept, 1863 P.C. Compton Pg. 77 No. 114 shows 1/4 Corner
used to set Center Sec 31 at intersecting lines