X — 6-2-1970 set ½ x 2' rod over corner (9' steel fence post) ①
11-20-1970 accepted ca dept rod set 4s. PZ. #723305
section corner south 32-33 Viola 107-12
North 4-5 Eyota 106-12.
6-1873 Hunter P226 no 229. S 32. Madden, Stillman
found large cedar stake center road with stones on
north and south sides.
1/16 west set stake 19.99½ M+L for line N N5°E.
no bearing to township line.
- mear north 39.89 (2632.74) to 1/4 cor set by testimony of settler
Williams causing considerable angle at E¼ 32.

5-1880 John Fraser P364 no 355 S 33. E Derby stat.
found large cedar stake P226. set by J Robinson (over)
Took W.T. Tree - S44°E 65 lks Willow Tree

Jonathan Williams, Joshua Fowler a surveyor, 16 years before. - Meas north 39.62. - RP to corner.
Willow 244E 65 lks. (42.9)

9-1930 J Kerr. B3 P56.
found cedar stake, drove 4' long rod down thru stake center - pointed limestone LE 37.0.
(Center old willow LE 43.0) - pointed rock NE 50.0.
This true witness by J.F. 1880

6-1957 Co Hwy Dept. 3/4" drill steel Sta 396+07.8
B206 P30 1953 -
Disc tele pole. NE 86.8 east Com fence 397+12.0
orange cap power P. NW 76.7 N27° W #258
" " P SW 40.35

#723305 (2)

Card # 2. South 32-33 Viola 107-12
North 4-5 Eyota 106-12.

1935 Co H D. B 75 P 20. found corner.
℄ road. 5.5' north of corner.
Sp T P. SW. 35.1 (also 38.4) - Sp Cor F.P. NW 43.35 (38.2)
Sp T.P. NE 50.95

1937 Co H D B 88 P 77. found iron fence post with Can & brass.
Cor F P. NW 43.35' - Tele pole. NE 50.95
Tele P. SW 35.1.
Meas west 2642.6.

6-3-70 Co surv. dug out drill steel and dug 2' north to center road. found J Kahr steel fence post top 2.6' down below drill rod. or .12' east and .05' south of drill rod broke glass & track ones post set 1/2" x 2' over at road level.

(over)

took additional tie by taping bearing on radio tower at N 56° 30' W and setting 3/4" x 3' rod on this AZ line southeasterly at 100' out in old cemetery lands. up 2" which came 62.3 ± north to ℄ road. as near ¼ mile from Co nail at S 31-32 was 5181.55 with 2640.35 at S 1/4 32. making 2641.2 from Co nail at S 1/4 32 to drill rod. S 1/4 32 was found 1.2 east of nail or 2640 even. post below drill rod was .12 east or 2640.12

11-20-1974.
checked above R.P. - the rod E had been bent!
The Rod set by C.H.D. for P.I. checked very close - accepted it & removed the rod 100' SE.

P.I's

Punch hole E. end R.C.M.P.	S.S.E.	48.41
Punch hole W. end R.C.M.P.	S.S.W.	48.95
Punch hole E. end R.C.M.P.	N.N.E.	47.95
C.S. Disc W. side PP #258	N.W.	76.55

Cor. stills 0.08' South ℄ of C.R. # 9.

Section corner South 32-33 Unit 107-12
North 4-5 Eyak 106-12
#723305

(3)

Code Notes

80.00 Set post & drive aluminum stake corner
Built mound with trench. Placed
SE Plug, NE Apple sticks.