X 7-16-76 CIM #723504 (1)

1/4 corner south 1/4 35 Viola 107-12
north 1/4 2 Eyota 106-12.

6-1874 Hunter P247 no 248, L2, P Brockway.
found stone in center road as corner, undisputed.
used corner to set center

Co Hwy dept 1953. Book 207. P4.
assumed corner.

Sp PP N 31.64
" FP NW 34.5
" Oak SW 37.0
" Cor FP NE 44.3

9-1927 B48 P35 assumed corner

30" oak	SW	36.4
36" C wood	SE	57.7
10" oak	SE	67.4

3' culv diagonal. Misc cor 4' W & S

7-16-76 Dug in "T" intersection for T. H.'s stone but found road had been cut to clay. Reset the corner M&L at 2635.05. Set a CIM over a 1¼" x 20" light piece of pipe. Corner falls 2' West of ℄ CR#7 running S and 2' S. of ℄ of C.R. #9 running E-W, and 6.0' N.E. of center of diagonal culvert taken as Rt ∠'s.

R.P.'s: CSD in pp #2566 NNW 36.14
Small punch hole in top N.W. End of 36" diagonal CMP NW 38.42
Punch hole in top of flange on SE end of 36" CMP SE 51.0
CSD in telephone pole # 44 SW 57.79

Gone N-S
to -- Sur post B.T.'s B-ork is S 67½ E 225
B-ork is S 24 W 53

1/4 CORNER 5'/4 35 V10CA 107-12
N'/4 2 E70TA 106-12 (2)
10/28/92 County Surveyor dug down to broken headed cinn 11" deep in blacktop C.R. #9. Set 60d spike @ surface, Local ties (Hook over 1.00'E, 1.00'N
#723504

5-21-93 CHD Took grading ties to Corner location before Constuction of CSAH #9

11-30-93 CHD set 3/8" Iron @ Corner location in Crushed Rock CSAH #9

11-29-94 CHD set 3/4" Brass plug in Concrete CSAH #9 as final Corner.