#730205 (1)

11-14-1964. found C/M as set by county.

section corner 2-3-10-11 Haverhill 107-13.
5-1872 Hunter P201 No 210 S 10, D Bulen, M Casey
J Coyle, & others
found stone set as corner, undisputed.
-16 south set stake M & L 19.97. 1318.02

5-1872 Hunter 202 No 210 S 1 & 2. J Moody.
A Raymond.
found stone P201 ticked by B tree in good condition
- mean east 39.74 to stake set M & L.
2622.84.

7-1902 21 Fraser P22 B. S11 Aron Pike, Pat Daly
found stone - 16 S set stone M & L 19.99 (1319.34
-16 east set stone 3x5x14 M & L 19.89 (1312.74 over -

Co Hwy Dept. B279 P2
found recorded stone set C/M over stone.
11-1964 J Kerr. found C/M. rechecked references

Disc	power pole.	S.S.W	52.01
"	pine	N.E.	63.31
"	elm.	NNE	46.26.
1" pipe by 2x2 hub & disc		N	66.4.

Sta 26+24.95 from 1/4 3-10 found stone 3x3 with t.
a PI 0° 5' left going east. Meas east to accum corner
at 1/4 2-11 2608.22 R 2625.48

1932 Co H D. B72 P26. found stone mon in place.
Sta 295+99.4 a PI Δ 0°04' left

#730205 (2)

Card # 2.

2-3-10-11 Haverhill 107-13

11-17-69. Meas south, found stone at 1319.9. Cont line south found 1/4 10-11 at 1320.0 further 1/16 stone exact center corner. 32' too far west or about east edge stone. R 1319.34

- east will meas black top line, only 2 to follow.

Hamlet 1872. 2622.84 39.74.

H Fraser. 1902. 2625.48 19.89 M&L 1312.74

Gov't Notes W. B. Verby 1853

80.00 Set a stone, corner post to 2, 3, 10 & 11

Bur Oak 9" in 5 12½ E 1½ 1K's

Bur Oak 9" in 5 82½ W 1.3E 1K's

Mark = trench