1-10-1964 set C/M over pipe in place. ①
#730305

section corner. 3-4-9-10 Haverhill 107-13.
5-1872 Hunter P201 No 210 & 10 O. Baker, Carey Coyle.
found short stake in road, tested 1 B.T. standing
and stumps of others cut.
-16 south set stake M & L 19.94 1316.04
-16 east set " " 19.93½ 1315.71.
-16 center " " intersection.

5-1873 Hunter P223 No 226 & 3 F Creecy, J Coyle.
found stake center road P201.
-16 North set stake M & L 19.88 (1312.08'

-over-

Corner 1½" pipe found which was placed from stake
when B tree was stab in place. (28° Bf oak NE 39.65-Herr No) South 2636.6 M.
7-1964 set C I M over pipe North 2626.3 West 2634.0 M&L.
Center north end small culvert (Covered up)
this old reference. NE 108.3.
Center south end culvert SE 66.6.
Dec power pole SE 47.5
" " " SW 46.85
" tele pole. NW 48.0

12-1932 Co H D B72 P23 found remains of old stake
Sta 241 + 25.5 ∠ 90°25' Rt Oak tree NE 39.0
stump & oak tree ended in relocating corner.
Gov't notes: W. B. Yerby - Nov. 1853 set Post To Sec Cr. 3-4-9-10
B.Tr. Beech 4" N52°W - 224) (Beech 12" N49°E 60 lks) (Beech 12" S12°E 98 lks
Beech 13" S65°W 147 lks.

Herr Set Pipe 1940 BK 22 P 40

Hanchett section corner 3-4-9-10 #730305 (2)

Good Notes -- reverse s.l.t

Aug 1996 Dean Strange of Peoples Coop
found 1" ± pipe, top pushed over towards
WSW, about .4' Deep.

Gov't Notes W.B. Verbil 1853

$0.00 Set A Stone corner post 3:1, 9-10

Bur OAK 14 in N 32 W 22¼ lks

" " 12 in N 49 E 60 lks

" " 12 in S 12 E 98 lks

" 13 in S 65 W 147 lks

(2)

2-8-99
EPA BB

"730305"e SEC COR 3-4-9-10 HAVERHILL
FOUND 1" PIPE/CAP BENT OVER DOWN 0.4'
PULLED PIPE AND SAWED OFF BENT PIECE.
RESET PIPE. PIPE DOWN 0.6', CORNER FALLS
1' E OF ℄ N-S HADLEY VALLEY RD NE &
0.5' N OF ℄ 65th ST NE
DISC IN PP # 34724 SE 47.45
DISC IN PP # 34722 SW 46.85