10-22-76 CIM #730506 (1)

1/4 Corner 5-6 Haver. 107-13.
3-1898 H Fraser P620 No 563 S5 Builder.
found stake in pile of stones as given H Hendrickson.
in U.S. Govt field notes. N Mich.
-16 North set stake on line and 19.97 1318.02.
then 20.69 1364.22 to section corner stone
-16 east set stake in pile of rock N&L 20.01
-16 center NW 1/4 5 set stake inters lines with
a passable stone by side (fine writing in record)

4-1901 H Fraser P56 SE 1/4 S6 H Groves.
found stake in pile of stones P620.

-over-

-16 south set stake & stone M&L 19.94 1/2 or 19.94 3/4
(1316.4'

1964 searched some for corner and 1/16 stake north.
1/16 corner in heavy head land. - 1/4 corner on rock knot.

1/16N (9-76) Dug 3'x3'x4' deep on W side of old corner post. Found nothing.

9-27-76 Dug  . Found nothing.

10-22-76 Set CIM over R.R. spike driven in bedrock as corner at intersection of line from E 1/4 Cor 5 over Center 5 and in line of main line of fence N. Corner comes 3' N. of Easterly post in group of three at fence intersection
R.D's Spike and CSD on S side of 6" Cedar ESE 100.30
Center of a shaft used as 3rd fence post in fence
West (bottom of post) WSW 27.5
Gov't meas. 40.70 :: 40.00

Haverhill 1/4 corner 5-6 #730506 E

Early Water on reverse side

Govt Notes WB. 1/4 bet 1853 North Random Sec
40.00 Sts to temp Sect. post
South 2' W on true line between Sec Sec
40.70 Sts to Section post in Mound of
Stone