X

#7306006 (1)

1/4 Corner West 1/4 6 Haver. 107-13
East 1/4 1 Cascade 107-14

6-1883 Hunter P283 No 374 L1 A Harrington
L Jaeglen.

Corner missing, found orig witness tree which put corner north of fence running west. Mr Jaeglen were fence west was set from orig stake. Could not find 1/16 stake north set survey No 77 but found stake & stone at 1/16 south set in same survey recorded as 19.82 chains - Meas from this corner north to fence west 19.84 chains so set boulder stone and

1308.12
1309.44

-over-

stake on west side in line fence west.
BT now N 6½° W 285 links instead of 244 links.
-16 North, set stake M & L 19.93½. 1315.71 39.87
-16 south found stake & stone at 19.84 chs 1309.44

In survey P53 no 77 by Hunter 2.44 66 1464 1464 161.04 2.85 66 171.0 171.0 171.0
-16 south M & L 19.82. 19.71
-16 north 20.00 then 19.91
39.71

Corner now ½" rod. by fence Post. set by J Kerr. These N pts due to the N/16
Spike in fence corner SW 25.73 } 5/8" rod
SE 13.66 } as ½ N
tree
(N. ½ rod set by Doug Betts 1959) - 15½' E of direct line N&S 1309 + M&L

B 35 P15 J Kerr 1947. ran line per on south to section corner.
Corner post at W ¼ 2619.0 section corner 5261 or 2642.0 S.
¼ post 46' E of direct line. B 86 P 39 found 5/8" 11-62 at ½ 1309.7

¼ Corner West ¼ 6 Haverhill 107-13 (2)
East ¼ 1 Cascade 107-14

4-19-1979 (1979 Remon. Book Page 30) #730606

At W¼ Cor 6: We found a 5"x9"x24" limestone standing on the West side of the N-S fence 8.3 South and .5 West of the iron by the corner post. We tested a Bur Oak NW of the stone as a possible bearing tree. The tree stands N6°W & N7°W 162.8 (246.7 lks) The tree is 40"x24" at the base and split into 2 trunks about 3' above ground and stands in Bob Sally's front yard.

4-18-79 At the 1/16th South (1979 Remon. Book Page 29,30,37) Found a ½" square iron at the 1/16th South The iron is 1' North of the north edge of

a blacktop driveway on the West side of T.H.63 and lies North the fence North and the fence East across T.H.63.

4-23-1979 Set up a point M&L from SE 1 to the stone found at the E.1/4 Cor 1 (came appx. 7' North of the sq iron fd) and a point (13.56 North of the sq. iron fd) M&L from SE 1 to the iron at the E1/4 Cor 1. Both points came in the cut of the driveway West. We did not dig.

4-18-1979 At the 1/16th North (1979 Person. Book Pages 29, 30, 37) We found McGhie iron at the 1/16th North. It was 11' North of the fence West and 2' East of the center of the old road N and South.

4-23-1979 We dug from a point 1' East and 1' South of the iron found for 3' East and 3' South by 4' deep. found nothing. Digging to cover M&L from NE Cor 1 to the stone found at the E1/4 Cor 1.

1/4 corner West ¼ 6 Hancock 107-13 #730606 | 5
East ¼ 1 Concorde 107-14

Civil Notes.
40.00 Set granite section post
Bk-Ok 14 N 3° W 244 lks
Dug crock.

6-21-88 The Co. Surveyor decided that because the Stone Found in 1979 was not the recorded boulder by T. Hunter we will use the location of John Kerrs Iron by the fence corner