#730609

1/4 corner Center 6 Haver 107-13

corner could never be found, neither 1/16 corner or 1/4 corner south of center 6.

Fence corner now assumed as true corner.

a solid steel rod now in place as corner

Mn/Dot shows iron is 1.1 ~~West~~ East and 12.3 ~~N.~~ South of theoretical cor.

1972 McGhie & Betts used 2" steel post as Corner

1/16 north - 3/8" Iron fd. by Mc & B. 1972

1/16 south - 5/8" Capped pipe set by McGhie & Betts

(over)

April, 1858 T. Hunter Pg 53 No 77 Shows Center Section
1/16 South 19.88 chs. M & L to 1/4 Post.
1/16 North 20 chs. then 19.98 chs. to 1/4 Post.
(See Survey for West 1/2 Sec. 6