#730804

4-8-1963 set C/M in place of limestone.

1/4 Corner 8-17 Haverhill 107-13.

5-1894 W Fraser P 549 No 509 of 17 P Robinson
J. Mahon.

Corner could not be found.
set stone and stake as corner. M&L 40.24.
-16 west set stake M&L 20.12.
-16 south " " " 19.90

4-1963 J Kerr.
found stone set C/M in place of stone.
corner lies near intersc. of fences north & east
corner lies about 660' south of where road turns north
from west

Good Works W.B. 1/2 by 1953 Easy Random 8017
40.00 Std A temp. Std. post

W+S on true line between S & N

39.95 1/2 Std A Std post in mound of
Earth and Soil N 30°47' E
Mark trench and pits planted
Osage Orange Std W+S of trench

4/5/90 FD CIM WITH BROKEN TOP LEANING NE 1/4
WE STAIGHTENED UP AND TOOK REFERECES BECAUSE
THERE WAS NOTHING BENEATH MON. PULLED CIM AND
SET 5' TELSPAR/CIC. THE CORNER LINES WITH
FENCE NORTH & IS 1/2' So. OF THE FENCE EAST, ± 1.0'
SOUTH OF C.P. TO FENCE E-N RP's
CSD IN P.P. 47286 SW 31.87', & OF N-S DRIVEWAY
CSD IN BRACE POST EAST 8.84' WEST 32.0', NAILED
CSD IN C.P. NORTH 1.22' SURVEY SIGN ON SOUTH
SIDE OF C.P.