X 8/15/80 SET 6' TEBSPAR PIPE/C.I.C. #730805 (1)

section corner. 7-8-17-18 Haverhill 107-13.
10-1877 Hunter P322 no 316 L7 J. Donnel & others.
found corner standing. L W B T standing, L E B T
stump marks plain. slight bearing variation on L W B T.
-16 north set temp stake M & L 20.05

-16 west P49 no 72 L ½ L7. M & L. 19.97.

8-1893 H Fraser P526 no 497 L18 P Jaffrey, Potter.
found stake P322 drove new stake.
- meas south 39.87 to stone set M & L.

5-1894 H Fraser P549 no 507 L17 P. Robinson
J Mahon.
-over-

found stake P526.
-16 east drone stake N 0 L 20.12.
- mear south 39.87

---

long 1" steel pipe near corner post now accepted as corner.

land in area very wet and boggy being at bottom of sharp slope northward. no fence south or east. Impossible to assume C/M would stay accurate in this wet spotty terrain.

Co H & D B 341. 1968 found iron pipe.
Mear north 515.99 to ℄ alignment. 665.61 to 1/2" prop cor in place.
Mear west to M'Elvie point as previously. 1000.0' NW ℄ road on west side big gully.

Haverhill section corner 7-8-17-18 (2)

Leah's Notes on reverse side #730805

Feb. 1858 T. Hunter Pg 49 No. 72 used Sec Cor.

1/16 west 19.97 chs. M&L to 1/4 Post

8-7-1980 (1980 Lemon BK) 1/16 East: Dug from 2' North of the traverse nail, North for 5' and West for 6' by 2' deep. Found probable stake hole appx 2" diameter with wood pieces and appx 6" long 5.4 North and 3.0 West of the t.n. and ½' East of the N-S fence.

stake { t.n. 6.3 SE
Spike 3.35 W

8-11-80 Sec. Cor 7-8-17-18 Searched around pipe in bog. Found pipe set at the base of post pumped out by water. Post seems to have been corner post of fences N & W.

8-12-80 Sec. Cor 7-8-17-18 Dug from a point 4½' North, North 6½', West 3' and East 1'± for Will Frasier stake. Found nothing

Gov't Notes W.B. Yorby 1853

80.00 Set A Station for post to 7, 8, 17 & 18

Bur Oak 12 in N 1c E 327 lks

" " 12 in S 10 E 124 lks

" " 8 in S 18 W 77 lks ? (Hunter and Fraser Surv S14W 177 lks)

Made Notch

(cont) The entire area is a bog and very wet but we were able to dig to clay because we were digging in the fence ridge running North.

8-15-80 See Cor 7-8-17-18: Set CIC or 6' piece of telspar (up 6") at the intersection of the line from SW 18 over the W 1/4 18 and the line from the SE Cor 8 over the S 1/4 Cor 8. Corner came 7.38 North and 1.00 West of the pipe (removed) that stood by the old corner post

(cont.)

Section Corner 7-8-17-18 Harvhill 107-13 (3)

#730805

8-15-1980 Continued:

RP's: Flange of Survey Marker Sign and Post
½' South of E-W Fence N 3.45

Sp & CSD NE side 20" Burr Oak S'ly 93.92 (slope)

Sp & CSD NW side 35" Burr Oak SSW 109.51 (slope)

Sp & CSD So. side 6" Elm used as corner post East 34.29

April, 1864 P.C. Compton Rg. 80 No. 120 used sec. Cor. 1/16 west set with B.T. (14" Burr oak S 72° W 52 lks.)