#730906 (1)

~~10-24-1963 set C/M over pipe.~~

Corner Correction: Set CIM 2.68 South and 1.87 East of Kerr's location.

1/4 Corner 8-9 Haverhill 107-13

1¼" pipe used as corner. Set M & L 2630.95 some years back by J Kerr.

10-1963 set C/M over pipe.

Disc tile pole.	SE	44.52.
" power pole	ENE	138.25
" knot & side pine	SE	83.45

Corner comes in center road running E & W

" " 1' west of fence north.


-Meas west 1 mile 5271.82. - N & L 2630.95 -Gen.

rod set at SW corner REA tower tract near where road turns southwesterly at 1714.58.
Govt Notes W.B. 1/4-1/4 1853
40.00 Std A section post
Burnt Stn N 1/2 W 1.41 1K's
" " Cm N 75 E 31.2 1K's

11-1964 JJK Book 88 Page 70
5-1965 JJK Book 89 Pages 77-79 Used corner to set Center Section 9. Measurement show measure from 1/4 Cor 8-9 North = 2636.6 - 15.27 = 2621.32
3-20-1979 Shot 1/16th North - Fence corner to Fences N-S-W See T.T. survey in back of Blue Book
5-9-1979 Dug with backhoe on the North side of the CIM in place. The old road is 3' deep and there was still post beneath the old road for two feet so we closed the hole

1/4 Corner 8-9 Haverhill 107-13 (2)
#730906

5-21-1979 Tried to dig again but there was still frost so ~~[illegible]~~ closed the hole. Projected a line set up 33' North of a row of large pines on the South side of a row of large pines on the South side of the road East, West toward the corner and the line fell 1 to 2 feet South of the C.I.M.

8-30-1979 We dug on the South side of Kerr CIM with the backhoe as follows . We found the remaining 8" of a stake (very fragile) 4½' deep and beneath the old road. Drove a ½" x 9" rod at the stake location and stood the remains of the stake alongside. Set a CIM over a ½" rod at the road surface. Removed

Kerr's CIM which was 2.68 North and 1.87 West. The corner is 2½ Sw. ℄ and 1' East of the fence running North.

RP's : CSD in pp# 34770 NE 136.85

CHD ~~Disc in tele phone pole~~ SE 41.00

11/6/89 FD CIM WITH BROKEN HEAD, TEL POLE SE GONE, CHAINED 136.71 (36°) NE TO CSD IN PP # 34770