11-24-1964 Note: Corner Could possibly go West ±9' = RWB 3-1979
set C/M in hard shell rock.

section corner 9-10-15-16 Haverhill 107-13 #73105

5-1872 Hunter P 201 No 210 S 10 A Bales, Carey, Coyle.

Note: found orig corner standing, tested by B true.

-16 north set stake N & L 19.94

-meas east from above 1/16 cor 39.70

11-1964 J Kerr B 89 P 77 Simm Koenig S 9.

corner comes in cattle pass connecting SE 1/4 9 and NW 1/4 15 8' wide 3' deg to hard bedrock.

- projected line from NW cor 10 over 1/4 9-10 2636.6 (as recorded ?) found 1/16 fence east south

-over-

of 1/4 9-10 to be very near 1318.3 or midway.
set C1M in bed rock in cattle trail.

Corner lines with main fences 4 ways.
Corner line 4' west of corner post terminal fence west
- nail in natural blaze in 24" red oak NE 45.85

used corner for line west to set S1/4 cor 9.
at 2622.9 M & L. a rough crooked line of
fences, showing some lines not originally surveyed.
11-1969. C1M said to be out of ground considerable. Must set
monument immediately. Now.

See T. H Book 4 p. 122 5-1876 T. Hunter unrecorded Survey

Gov't notes. W.m Yerby Dep Surv. Nov. 1853
80.00 chs. set Sec. post / B.T's Br. oak 8" N65°W 53 lks / B.Ok 9" S52°E 47 lks
to Secs. 9-10-15-16 Br oak 20" N 70°E 58 " B. Oak 22" S45°W 40 lks