1 9-11-69 set CIM over 3/4 x 16" rod with orig stone or Saids #731104 (1)

1/4 corner 11-14 Haverhill 107-13

7-1962 H Fraser P22B S11 & Pike P Daly found remains of old fence post owned by H M. Richardson that he put this post just on east side of old stake when standing. and showed personally how post was placed in relation to corner when standing.

- set stone 4 x 5 x 20 as corner.
- Meas west to corner fence post accepted as SW cor 11-39.88 this post as SW 11 in doubt.

9-3-69 J Kerr. Run 1/16 line from farm fence running east into Sec 13 betw NW 13 and 1/4 13-14 which was proven close to correct, went to 1/16 set M&L between. SW 11 and 1/4 14-15 set Nail on this line in line fence north and near 1317.5 where set nail at 1300 and 1317.5 some 3' west of N-S fence stone & still in place should be in that area will search later Nail at 1300 corner N edge plum tree 1317.5 by rag on fence.
9-8-69 found stone in area about 1 hour with probe soil very hard dig 9-11-69. removed stone down 16" 4x5x25" set C1M one 1"x10" rod & glass with stone south side C1M & broken off steel & staged post up 15" about 6" WSW. C1M down about 4 inches Corner very little east of under fence - 22.5' north to tall large cedar post used as fence terminal thought by owners as near corner 26' south to small plum tree with four main stems 3" in diameter. Corner lies some 75' north of small natural watershed west

Haworth 11 1/4 corner 11-14

#731104 (2)

Cont Notes on reverse side

Govt Notes W.B. Hurley 1853 East Random
11+14

40.00 Std A tramp Std post

West on true line between 11+14 course

40.02½ Std A Std post 7°12' E

Bur Oak 7.in N 50 E 181 lks

Bur Oak 10.in S 50 W 26 lks