1-9-3-69 set C/M over old 2" pge union in pass old COR post.
#731105 (1)
section corner. 10-11-14-15 Haver. 107-13.
5-18 72 Hunter P201 No 210 S10 O Bulen, M Casey
J. Coyle & others
found burned out BT but some marks still left.
corner came in cultivated field set temp stake.
- Meas north 39.94 To stone · 4x6x20 set M & L.
note - corner set as 1/4 10-11 set direct line & midway
next survey doesn't agree - likely diff in S W cor 10
E

1-1902 St Fraser P22B S11 O Pike. P Daly.
used corner past for this survey without due
-over-

proof. - Meas west. 39.74 to proven corner.

Meas- east 39.88 to " "

as no post was here P201 but witness tree still plain by nearly burned up. and 1/4 corner north set M & L. & H Fraser this survey claims 1/4 cor. North 22 1/2 chs too far west - one wonders if past Fraser found itself too far west at section corner.

9-3-69 J Kerr found corner post. 3' north of wood cor post used there to hold N-S fence wires. so many old wires on it that it was never removed. top 8" of stub completely gone would never have found if top wasn't in evidence - set 2" pipe union with 4" lead up nipple on each side of union below C/M. with 1 1/4" pipe up 3' ± .7 south of C/M. old post up 14" north of C/M came nearly under N-S fence no E-W fences. 36' N to pepsi in PP# 19711

16 south drove 1/2" rod & road Midway not line at 13 13.65 line fence North.

#731105

(2)

Card # 2. Sec Cor 10-11-14-15 Haverhill

W Fraser set 1/16 stone 3x5x14 north & old. 107-13
past M & L to 1/4 10-11 a stone found as
recorded by Hunter 4x6x20 set M & L 39.94 (2636.04
- Meas now 19.99 or (1319.34' and stone at
1/4 10-11 now. 22½ lks 14.85 too far west to be on
direct line
9-16-1969. found 1/16 stone as recorded north & old post (now
CIM) at 1318.2 Record Hunter 1318.02 Fraser 1319.34.

Gen'l Notes
over

Gov't Works W.B. Hurley 1853

$0.00 Std to Std post to Std 10, 11, 14 & 15

Bur Oak 10 in W 3s E 55s 1 Ks

Mark to touch